

- ATTENTION:**
- GENERAL MANAGER
 - PARTS MANAGER
 - CLAIMS PERSONNEL
 - SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

© 2016 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2010-16MY Legacy and Outback
 2011-16MY Impreza
 2014-16MY WRX&STI
 2013-15MY Forester

NUMBER: 18-186-16

DATE: 05/04/16

SUBJECT: Service Manual Corrections

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	PAGE	DESCRIPTION OF CHANGE
2016	Legacy & Outback	Engine 1	IN9H4D0)-2,3	New image
		Body	SL-77,78	New Impact Sensor adjustment steps.
2015	Legacy & Outback	Engine 1	IN9H4D0)-2,3	New image
2014	Legacy & Outback	Transmission	CVT(diag)-50-53	Diagnostic steps changed for DTC P0841
		Body	LAN(diag)-71	Diagnostic steps changed.
		Wiring System	WI-254,256	New wiring diagrams.
2013	Legacy & Outback	Transmission	CVT(diag)-48-51	Diagnostic steps changed for DTC P0841
		Body	LAN(diag)-78	Diagnostic steps changed.
		Wiring System	WI-250,252,254	New wiring diagrams.
2012	Legacy & Outback	Transmission	CVT(diag)-49-51	Diagnostic steps changed for DTC P0841
		Body	LAN(diag)-15,49	Diagnostic steps changed.
		Wiring System	WI-213,215,216	New wiring diagrams.
2011	Legacy & Outback	Transmission	CVT(diag)-49-51	Diagnostic steps changed for DTC P0841
		Body	LAN(diag)-15,49	Diagnostic steps changed.
		Wiring System	WI-194,196	New wiring diagrams.

Continued...

YEAR	MODEL	SECTION	PAGE	DESCRIPTION OF CHANGE
2010	Legacy & Outback	Transmission	CVT(diag)-49-51	Diagnostic steps changed for DTC P0841
		Body	LAN(diag)-14,48	Diagnostic steps changed.
		Wiring System	WI-194	New wiring diagrams.
2015	Forester	Transmission	CVT(diag)-91-95	Diagnostic steps changed for DTC P0841
		Chassis	VDC(diag)-96	Diagnostic steps changed for DTC C1733
		Wiring System	WI-456	New wiring diagrams.
2014	Forester	Transmission	CVT(diag)-60-64	Diagnostic steps changed for DTC P0841
		Chassis	VDC(diag)-97	Diagnostic steps changed for DTC C1733
		Wiring System	WI-462	New wiring diagrams.
2013	Forester	Chassis	VDC(diag)-73	Diagnostic steps changed for DTC C1733
2016	Impreza	Transmission System	CVT(HEV)(diag)-104-107	Diagnostic steps changed for DTC P0841
		Transmission System	CVT(w/o HEV)(diag)-91-94	Diagnostic steps changed for DTC P0841
		Body	SL-77,78	New Impact Sensor adjustment steps.
2015	Impreza	Transmission System	CVT(HEV)(diag)-86-89	Diagnostic steps changed for DTC P0841
		Transmission System	CVT(w/o HEV)(diag)-72-75	Diagnostic steps changed for DTC P0841
2014	Impreza	Transmission System	CVT(HEV)(diag)-62-65	Diagnostic steps changed for DTC P0841
		Transmission System	CVT(w/o HEV)(diag)-52-55	Diagnostic steps changed for DTC P0841
2013	Impreza	Transmission System	CVT(diag)-46-49	Diagnostic steps changed for DTC P0841
2012	Impreza	Transmission System	CVT(diag)-49-51	Diagnostic steps changed for DTC P0841
2011	Impreza	Chassis	VDC(diag)-77	Diagnostic steps changed for DTC C0056
2016	WRX & STI	Engine 2	EN(w/o STI)(diag)-320,322	Diagnostic steps changed for DTC P0616
		Transmission	CVT(diag)-70-73	Diagnostic steps changed for DTC P0841
		Body	SL-77,78	New Impact Sensor adjustment steps.

Continued...

YEAR	MODEL	SECTION	PAGE	DESCRIPTION OF CHANGE
2015	WRX & STI	Engine 2	EN(w/o STI)(diag)-292,294	Diagnostic steps changed for DTC P0616
		Transmission	CVT(diag)-69-72	Diagnostic steps changed for DTC P0841
2014	WRX & STI	Chassis	VDC(diag)-83	Diagnostic steps changed for DTC C0056

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.