

NUMBER: 08-050-16

GROUP: Electrical

DATE: April 22, 2016

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 16-032. ALL APPLICABLE SOLD AND UN-SOLD RRT VINS HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Headlamps May Be Out Of Adjustment Or Alignment.

OVERVIEW:

This bulletin involves adjusting the headlamps to specified alignment.

MODELS:

2016	(DJ)	Ram 2500 Pickup
2016	(D2)	Ram 3500 Pickup
2016	(DD)	Ram 3500 Cab Chassis
2016	(DP)	Ram 4500/5500 Cab Chassis
2016	(DF)	Ram 3500 10K LB Cab Chassis

NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA and LATAM.

NOTE: This bulletin applies to vehicles built on or before March 14, 2016 (MDH 0314XX) without Auto Level Rear Air Suspension (Sales Codes SEB).

SYMPTOM/CONDITION:

The customer may describe that the headlamps are out of alignment or oncoming vehicles are flashing their bright lights at them.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition, perform the Repair Procedure.

08-050-16 -2-

REPAIR PROCEDURE:

- 1. Are the headlights out of adjustment?
 - a. YES>>> Proceed to Step #2 and align the front headlamps.
 - b. NO>>> This bulletin has been completed, use LOP (08-50-34-96) to close the active RRT.
- 2. Refer to the detailed service procedures available in DealerCONNECT>
 TechCONNECT under: Service Info> 08 Electrical> 8L Lamps and Lighting>
 Lamps/Lighting Exterior> Standard Procedure> Standard Procedure Front Lamp Aiming.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
08-50-34-96	Headlamp Alignment - Inspect - W/Out Sales Code SEB - Auto Level Rear Air Suspension (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.2 Hrs.
08-50-34-97	Headlamp Alignment - Inspect & Aim - Includes one or both: W/Out Sales Code SEB - Auto Level Rear Air Suspension (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.3 Hrs.

FAILURE CODE:

ZZ	Service Action	
----	----------------	--