



**NUMBER:** 08-030-16

**GROUP:** Electrical

**DATE:** March 19, 2016

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**THIS BULLETIN SUPERSEDES SERVICE BULLETIN 08-125-15, DATED DECEMBER 19, 2015, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **\*\*ASTERISKS\*\*** AND INCLUDE ADDITIONAL MARKET INFO, VEHICLE LINE ADDED TO THE RRT, REPAIR PROCEDURE, AND LABOR OP.**

**THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 15-125. ALL APPLICABLE UN-SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE UN-SOLD VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. FOR VEHICLES NOT INCLUDED IN THE RRT VIN LIST, APPLICATION OF THIS SERVICE BULLETIN TO SOLD UNITS IS BASED UPON THE CUSTOMER EXPERIENCING THE SYMPTOM/CONDITIONS. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.**

**SUBJECT:**

Premature Headlamp Bulb Failure

**OVERVIEW:**

This bulletin involves replacement of both headlamp bulbs.

**MODELS:**

- \*\*2015** (WD) Dodge Durango**\*\***
- 2015 (LD) Dodge Charger

**NOTE: **\*\*This bulletin applies to vehicles within the following markets/countries: NAFTA, LATAM, APAC and EMEA.\*\*****

**NOTE: **\*\*This bulletin applies to WD vehicles built on or after July 01, 2015 (MDH 0701XX) and on or before December 07, 2015 (MDH 1207XX) equipped with Halogen headlamps (Sales Code LMB).\*\*****

**NOTE: This bulletin applies to LD vehicles built on or after July 01, 2015 (MDH 0701XX) and on or before September 15, 2015 (MDH 0915XX) equipped with Bi-function halogen projector headlamps (Sales Code LMC).**

**SYMPTOM/CONDITION:**

The customer may experience premature headlamp bulb failure.

**DIAGNOSIS:**

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition listed above, perform the Repair Procedure.

**PARTS REQUIRED:**

Qty.	Part No.	Description
2	L0009012LL	Headlamp Bulb

**REPAIR PROCEDURE:**

1. \*\*Remove both headlamp bulbs and discard them. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 08 Electrical> 8L - Lamps and Lighting> Lamps/Lighting - Exterior> Unit, Front Lamp> Removal> Bulb.
2. Install both new headlamp bulbs. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 08 Electrical> 8L - Lamps and Lighting> Lamps/Lighting - Exterior> Unit, Front Lamp> Installation> Bulb.\*\*

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
**08-50-32-92	Headlamp Bulb, Replace Both Left And Right (WD Vehicle) Sales Code LMB (0 - Low Skilled)	6 - Electrical and Body Systems	0.3 Hrs.**
08-50-32-91	Headlamp Bulb, Replace Both Left And Right (LD Vehicle) Sales Code LMC (0 - Low Skilled)	6 - Electrical and Body Systems	0.2 Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------