

2/26/16

MY13, 14, 15 PF

GPOP - Issue Review System

Part Number: 68210293A\$

Part Description: MODULE, Transmission Control

Issue This generic TCM must be flashed with the ignition in the accessory position.

Description: Attempts to flash with the ignition in the run position may result in flash failures.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.