

March 16, 2016

MY11 & MY14 LC, LD, LX

GPOP - Issue Review System

Part Number: 68037593A\$, 68043927A\$

Part Description: Beam, Upper Load Path & Beam, Inner Load Path

Issue Description: There are net, form and pierce features on the LC/LD/LX Front Fender. These net, form and pierce features are only captured during the line assembly process. It is not a service operation within the assembly line. For repair, the technician must locate, drill and shim the Load Paths, as required. This will allow for the adjustability necessary.~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
