

From: [Broadcast Messaging System](#)
To: [DL-BMS_Message_Monitors](#)
Subject: Supplementary Page Needed in Owner's Manual SIB 84 09 16
Date: Tuesday, September 27, 2016 3:22:54 PM

Publish Date: September 27, 2016
From: Parts Logistics
Expiration Date: October 11, 2016

DCSnet Message
Important



Subject: **Supplementary Page Needed in Owner's Manual SIB 84 09 16**

To: All BMW Parts and Service Managers

Re: Supplementary Page Needed in Owner's Manual SIB 84 09 16

Dear Parts and Service Managers,

A Service Information Bulletin (SIB 84 09 16) involving 2 series (F22, F23, F87), 3 series (F30, F31, F34, F80), and 4 series (F32, F33, F36, F82, F83) operator's manual. The operator's manual of the affected vehicles does not contain the required information on wireless smartphone charging accessory.

A supplementary sheet must be added to the operator's manual before vehicle delivery.

Please review SIB 84 09 16 in its entirety for more information.

Thank you,
Parts Logistics

Attachments:

No Attachments No Attachments

Recipients: BMW Passenger Cars, CC-All
BMW Passenger Cars, All Offerings, All Regions, All Areas, Service, All
BMW Passenger Cars, All Offerings, All Regions, All Areas, Parts, All

