



SI B51 34 16
Body Equipment

August 2016
Technical Service

RAISING OF WIND DEFLECTOR AT A HIGH SPEED

MODEL

F33 (428i Convertible)	F33 (428i xDrive Convertible)	F83 (M4 Convertible)
------------------------	-------------------------------	----------------------

SITUATION

Unintentional lifting of the wind deflector occurs at a high speed and it is perceived that it may possibly detach.

CAUSE

Rear seat backrest not locked. This is not visually detectable at first glance.



CORRECTION

Make the customer aware of the proper rear seat engagement.

PROCEDURE

Demonstrate to the customer how to properly latch the rear seat mechanism.

Inform them that this latch must be fully engaged to prevent the wind deflector from raising up while driving.

Explain that the wind deflector is firmly anchored by the front bolt therefore there is no danger of loss of the wind deflector at speed.

WARRANTY INFORMATION

Not applicable, information only.

[Copyright ©2016 BMW of North America, Inc.]