



SI B51 23 16
Body Equipment

July 2016
Technical Service

SNOW IN ENTRANCE AREA

MODEL

I12 (i8) Vehicles produced until August 2015.

SITUATION

Snow or dust may accumulate in entrance area




CAUSE

Excessive clearance in door sill area.

CORRECTION

Replace entrance cover and entrance molding on both sides.

PROCEDURE





PARTS INFORMATION

Part Number	Description	Quantity
51 77 7 428 971	Door entrance panel, left	1

51 77 7 410 033	Door entrance molding, left	1
51 77 7 428 972	Door entrance panel, right	1
51 77 7 410 034	Door entrance molding, right	1

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Defect Code:	51 47 19 41 00	
Labor Operation:	Labor Allowance:	Description:
51 47 070	Refer to KSD2	Removing and/or installing or replacing cover plates on both front door entrances (Main work)
Or:		
51 47 570	Refer to KSD2	Removing and/or installing or replacing cover plates on both front door entrances (Plus work)

If you are using a Main labor code for another repair, use the Plus code labor operation 51 47 570 instead.

[Copyright ©2016 BMW of North America, Inc.]