



HALOGEN HEADLIGHT ADJUSTMENT PROCEDURE**MODEL**

F30 (3 Series)	F31 (3 Series Sport Wagon)
----------------	----------------------------

SITUATION

Halogen headlights may be misaligned (aimed too low or high).


CORRECTION

Re-adjust the headlight (only low beam)

PROCEDURE

After the headlight unit is replaced or when a headlight of a vehicle in the shop is misaligned; the headlight must be aligned.

1. To perform the headlight alignment you can use a headlight aligner or follow the attached procedure.



2. Adjust the headlight by following ISTA procedure:

- REP 6310PRF "Test requirements for headlights vertical aim adjustment"
- REP 6310004 "Adjusting headlights"



Note: The recommended and tested headlight aligner can be purchased from BMW Center

Solution website:

<http://www.bmwcentersolutions.com/>

WARRANTY INFORMATION

Not applicable.

ATTACHMENTS

View PDF attachment [B630616_Adjustment_Procedure.](#)

[Copyright ©2016 BMW of North America, Inc.]