

From: [Broadcast Messaging System](#)
To: [DL-BMS_Message_Monitors](#)
Subject: Workshop Technology Update: ISTA/P 3.59.1 Release Information
Date: Thursday, July 07, 2016 10:51:11 AM

Publish Date: July 07, 2016
Technical Service
From: July 21, 2016
Expiration Date:

DCSnet Message
Important



Subject: **Workshop Technology Update: ISTA/P 3.59.1 Release Information**

Subject: ISTA/P 3.59.1 Release Information

Priority: Important

Message Recipients: Service Managers, Shop Foremen and Technicians

Message Text:

Thursday July 7, 2016, ISTA/P 3.59.1 will be released to all dealers.

ISTA/P 3.59.1 contains the following software corrections:

Models	Fault elimination for
G12	KOMBI - incorrect display of units in 'Sports' mode
G12, F48 F54 F55 F56 F57	KOMBI - inaccurate time display
F01 F02 F06 F07 F10 F12 F15 F16	Head-Up-Display: erroneous display for roundabouts during active route guidance

Refer to TIS \ Technical Documentation \ Diagnosis and Programming for the ISTA/P 3.59.1 release notes

It is important when performing any repairs and programming on G12 (7 Series) vehicles, that only ISTA/P 3.59.1 or higher be used.

If you have any questions you can direct them to: Paul.Labrie@bmwna.com

Sincerely,

Paul Labrie

Technical Service

Attachments:
No Attachments No Attachments

Recipients: MINI Passenger Cars, Service, All Regions, All Areas, All Departments, All Personnel
BMW i, Service, All Regions, All Areas, All Departments, All Personnel
BMW SAV (Light Trucks), Service, All Regions, All Areas, All Departments, All Personnel

