



SI M51 07 16
Body Equipment

August 2016
Technical Service

ACTIVE REAR SPOILER IS STIFF MOVING IN AND OUT

MODEL

R58 (Cooper Coupe)	R59 (JCW Coupe)
--------------------	-----------------

SITUATION

The active rear spoiler binds while moving in and out. It also may not operate properly.

CAUSE

The mechanics of the active rear spoiler are stiff and/or show corrosion.

CORRECTION

Lubricate the rear spoiler mechanism.

PROCEDURE



1. Remove any corrosion.
2. Treat the mechanics of the active rear spoiler with Universal lubricating spray (Part number 83 23 2 327 735)

PARTS INFORMATION

Part Number	Description	Quantity
83 23 2 327 735	Universal lubricating spray (12oz)	1

WARRANTY INFORMATION

Covered under the terms of the MINI New Passenger Car Limited Warranty.

Defect Code:	51 62 02 34 00	
Labor Operation:	Labor Allowance:	Description:
51 99 000	3 FRU	Work time to lubricate rear spoiler mechanism (Main work)
Or:		
51 99 000	1 FRU	Work time to lubricate rear spoiler mechanism (Plus work – Vehicle is already in the workshop)

And:

Sublet – Bulk Materials

Sublet Code 4	\$1.00	Reimbursement for the used quantity of Universal lubricating spray (Please do not use part numbers for claim submission)
---------------	--------	--

[Copyright ©2016 BMW of North America, Inc.]