



SUBJECT

Steering wheel rubs/brushes against the steering column trim

MODEL

I01 (i3, i3REx)

SITUATION

When the steering wheel is moved, it rubs/brushes against the steering column trim.

CAUSE

Rear steering wheel trim.

PROCEDURE

	<p>Replace the rear trim of the steering wheel with P/N 32 30 6 866 328. Care must be taken to ensure that the trim and the button block lock cleanly into place on the multifunctional steering wheel.</p>
--	---

PARTS INFORMATION

Part Number	Description	Quantity
32 30 6 866 328	Cover for steering wheel, rear	1

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Defect Code:	32 33 08 41 00	
Labor Operation:	Labor Allowance:	Description:

32 33 000	Refer to KSD	Removing and installing or replacing steering wheel
And:		
32 99 000	1 FRU	Work time to replace the rear trim of the steering wheel

If you are using a Main labor code for another repair, use the Plus code labor operation 32 33 500 instead.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowance.

Work time labor operation code 32 99 000 is not considered a Main labor operation. Also, since the “work time” FRU allowance to be claimed is specified, a separate punch time is not required.

[Copyright ©2016 BMW of North America, Inc.]