

**SUBJECT**

Error Message for Active Sound Design (ASD) When Programming with ISTA/P

MODEL

F16 (X6)

Vehicles produced up to August 9, 2015.

SITUATION

A fault message comes up for the Active Sound Design (ASD) control unit when executing an ISTA/P measures plan.

CAUSE

ISTA/P Software error.

CORRECTION

None needed.

X6 vehicles produced prior to August 2015 did not come equipped with an ASD module.

PROCEDURE

If you receive an error message for the ASD while programming, ISTA/P will suggest a special measure of the module.

1. Do not accept this special measure. Instead continue programming.
2. You will again see an error message for the ASD which can be ignored and programming will continue.

WARRANTY INFORMATION

For information only

[Copyright ©2016 BMW of North America, Inc.]