



---

This Service Information bulletin supersedes SI B13 03 15 **dated March 2015** and **replaces** SI B13 04 13 **dated March 2014**.

**SUBJECT****N20, N26, N55, N63TU, S63TU and S55 Engines: Bosch Injector ETK Part Number Error****MODEL****NEW**

E70(X5)

E71 (X6)

E84 (X1)

E82 (1 Series Coupe)

E88 (1 Series Convertible)

E89 (Z4)

E90 (3 Series Sedan)

E92 (3 Series Coupe)

E93 (3 series Convertible)

F01 (7 series Sedan)

F02 (7 Series Sedan LWB)

F02H (7 Series Active Hybrid 7)

F06 (6 series Gran Coupe)

F10 (5 Series Sedan)

F10H (5 Series Active Hybrin 5)

F12 (6 Series Convertible)

F13 (6 Series Coupe)

F15 (X5)

F16 (X6)

F22 (2 Series Coupe)

F23 (2 Series Convertible)

F25 (X3)

F26 (X4)

F30 (3 Series Sedan)

F30H (3 Series Active Hybrid 3)

F31 (3 Series Sports Wagon)

F32 (4 Series Coupe)

F34 (3 Series Gran Turismo)

F36 (3 Series Gran Coupe)

F80 (M3 sedan)

F82 (M4 Coupe)

F83 (M4 Convertible)

F85 (X5M)

F86 (X6M)

#### **NEW SITUATION**


The current version of the ETK incorporates multiple part number errors for the Bosch type injectors. Ordering the injectors by VIN number or manual identification in ETK may result in an incorrect part number.

#### **NEW PROCEDURE**

1. Identify the currently installed injector part number using a borescope.
2. Enter that injector part number into Atlas and order the quantity needed to repair the vehicle. Supersessions in Atlas are correct.

Bosch Injector Overview:

--	--



Bosch injector with black plastic housing (1).  
Injector part number location (2).



Injector part number location (1).

When the ETK is corrected, this SI B will be updated.

**WARRANTY INFORMATION**

Not applicable.

[ Copyright ©2016 BMW of North America, Inc. ]