

February 2016 Technical Service

SUBJECT

Location of Anti-Tampering Screws for SCR Components

MODEL

F02 (7 Series Sedan)

F10 (5 Series Sedan)

F25 (X3)

F30 (3 Series Sedan)

F31 (3 Series Sports Wagon)


With the N47T or N57T diesel engine

SITUATION

Anti-tampering screws are not being used for the underbody cover around the SCR metering valve.

CAUSE

Anti-tampering screws are not being replaced during service when the underbody protection panels are removed.



Anti-tampering screws (1).

INFORMATION

Refer to the attachment for proper location of the screws

PARTS INFORMATION

Part Number	Description	Quantity

07 14 7 367 231	Fillister head screw	Up to 3
-----------------	----------------------	---------

WARRANTY INFORMATION

Not applicable.

ATTACHMENTS

View PDF attachment **B160116** Location of anti-tamper cover.

[Copyright ©2016 BMW of North America, Inc.]