



SI B51 05 16
Body EquipmentBody Equipment

February 2016
Technical Service

SUBJECT

Steering Column Upper Joint Cover Trim Shows Creasing

MODEL

F48 X1 (xDrive 28i)

Produced to March 30, 2015

SITUATION

Customer can see a crease in the upper steering column joint trim, especially when moved into the lower position.


CAUSE

Tensioning of the upper steering column joint trim

CORRECTION

Replace joint trim.

PROCEDURE

	<ol style="list-style-type: none"> 1. Confirm the upper joint trim is creasing. 2. Use Repair Instruction 32 31 003 to replace the steering column joint trim.
---	--

PARTS INFORMATION

Part Number	Description	Quantity
51 45 9 292 193	Joint cover, steering column, upper	1

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light

Trucks.

Defect Code:	61 30 51 41 00	
Labor Operation:	Labor Allowance:	Description:
32 31 004	Refer to KSD2	Removing and installing or replacing upper section of steering column joint trim panel (Main work)
OR:		
32 31 504	Refer to KSD2	Removing and installing or replacing upper section of steering column joint trim panel (Plus work)

If you are using a Main labor code for another repair, use the Plus code labor operation 32 31 504 instead.

[Copyright ©2016 BMW of North America, Inc.]