



**SUBJECT**

**Delivery Stop: Sunroof – Possible Leak**

**MODEL**

i01 (i3 Battery Electric Vehicle)

**SITUATION**

A Delivery Stop has been issued on i3 BEV vehicles produced from December 09, 2015 to January 22, 2016. Vehicles are equipped with a sunroof as part of the Shadow Sport limited edition. The sunroof may not be properly sealed, so that leaks could possibly develop. This bulletin will be updated with repair instructions and warranty information when it becomes available.

Affected vehicles can be identified with a “Vehicle Comment” in DCS Warranty Vehicle Inquiry or ISPA Light with the description:

**“A delivery stop has been issued for this vehicle. Dealers must ensure that all Campaigns are completed before retail delivery to the customer. See Service Information Bulletin B54 01 16 for repair instructions.”**

**The chassis numbers of the affected vehicles are listed below:**

V556281
V556282
V556284
V556286
V556287
V556288
V556289
V556334
V556337
V556338
V556344
V556373

**ATTACHMENTS**

View PDF attachment [B540116 Attachment 1](#).

[ Copyright ©2016 BMW of North America, Inc. ]