

March 2016 Warranties

SUBJECT

Supply and Retrofit an Additional Key Radio Remote Control (FOB) "without" Display

MODEL

G12 (740i, 750i and 750i xDrive Sedans)

From the start of production (SOP), up to and including February 29, 2016 with option code 03DS

INFORMATION

The following G12 (7 Series Sedan) vehicles:

- 740i Sedan and the 750i xDrive Sedan produced from July 2015 to February 2016; and the
- 750i Sedan produced from November 2015 to February 2016,


With the Display Key (option code 03DS) originally came accompanied with:

• One complete remote key fob* (with valet insert) and one valet insert.

G12 (7 Series Sedan) vehicles with this option code produced on or after March 2016, as a result of a market analysis and in anticipation of potential customer requests, now come accompanied with:

• Two complete remote key fobs* (with valet insert) and one valet insert.

SITUATION



While mid-year model/equipment level changes to vehicles commonly occur within the automobile industry, as previously announced, BMW of North America, LLC ("BMW NA") has decided to offer this "newer equipment level" to eligible early-adopter G12 (7 Series Sedan) owners/customers that qualify.

^{*}Radio remote control without display

PROCEDURE

For the vehicles noted above, if an owner/customer requests an additional key remote key fob*, your center can order, supply and retrofit "one additional or a second" complete key remote fob* at no cost to him or her.

Your center must order the specific remote key fob that matches the customer's vehicle (VIN) and the valet insert to create a complete key fob.

The standard secure key ordering process and the applicable "manually teaching-in the new remote" procedure apply. Please see the attachments for more information

Important note

Reimbursement for this vehicle-specific retrofit procedure can only be submitted "one-time."

Before ordering another complete key remote fob for a eligible vehicle, always check the DCSnet Warranty Vehicle Inquiry's "Repair History (Claims)" section for "Defect Code 85 10 03 01 NA."

PARTS INFORMATION

Please refer to the Electronic Parts Catalog (EPC/ETK), using the customer's VIN to locate the corresponding part number.

Part Number	Description	Quantity
Refer to ETK	Radio remote control without display	1

And:

Part Number	Description	Quantity
51 21 7 409 076	Integrated key (Slide-in key)	1

In order to make the process convenient for your center and our customers, all key coding, programming and related processing will be handled by Parts Distribution in Nazareth.

WARRANTY INFORMATION

The retrofit procedure outlined in this bulletin can be submitted for reimbursement "one-time" on an eligible vehicle during the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks' coverage period of 48 months or 50,000 miles, whichever occurs first.

Reimbursement for this key fob retrofit procedure is through normal claim entry utilizing the following information.

Defect Code:	85 10 03 01 NA	G12 Additional Customer Key Request

Your center may only submit a claim for the VIN-specific BMW part numbers for the "Radio remote control without display" and the "integrated key" that were ordered and retrofitted to the

vehicle

The simple process of key activation can be completed within minutes, this labor (FRU) is not be eligible for reimbursement.

ATTACHMENTS

View PDF attachment **B010616 BMW Key Bulletin2013**.

View PDF attachment **B010616 Key Manually Teach-in**.

[Copyright ©2016 BMW of North America, Inc.]