



SI B51 14 15
Body Equipment

March 2016
Technical Service

This Service Information bulletin supersedes SI B51 14 15 **dated May 2015**.

SUBJECT

Grinding Noise from Steering Wheel When Turning

MODEL

I03 (I01)

NEW Produced from September 30, 2014 to December 16, 2015

SITUATION

Customer complains of a noise from the steering wheel while driving.

CAUSE

Due to insufficient gap, the steering column lower shroud rubs against the steering wheel.

CORRECTION

Modify the lower shroud support clip.

PROCEDURE

Refer to the attachment for the repair procedure.

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Defect Code:	51 31 03 39 00	
Labor Operation:	Labor Allowance:	Description:
32 31 020or	Refer to KSD2	Removing and installing or replacing lower section of steering column trim
And:		
NEW 51 99 000	1 FRU	Work time to modify the lower section clip of the steering column trim

If you are using a Main labor code for another repair, use the Plus code labor operation 32 31 520 instead.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowance.

NEW Work time labor operation code 51 99 000 is not considered a Main labor operation. Also, since the “work time” FRU allowance to be claimed is specified, a separate punch time is not required.

[Copyright ©2016 BMW of North America, Inc.]