



SUBJECT

The Horns Fail to Operate

MODEL

i8 (I12)

SITUATION

When the horn is activated, one or both horns fail to work.

CAUSE

Mechanical defect of the horn(s)

CORRECTION

Replace horn(s) if directed by test plan.

PROCEDURE

1. Perform diagnosis with ISTA using the Fanfares test plan. The test plan can be accessed using the following path: Function Structure / Body / General vehicle electrical system / Fanfares.
2. Replace the horn(s) based on the test plan results.

Always connect a BMW approved battery charger / power supply.

PARTS INFORMATION

Part Number	Description	Quantity
61 33 7 410 479	Horn, high pitch	1
61 33 7 410 478	Horn, low pitch	1

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Defect Code:	61 33 00 12 00	
Labor Operation:	Labor Allowance:	Description:
00 00 006	Refer to KSD2	Performing "vehicle test" (with vehicle diagnosis system – checking faults)
And:		

61 25 910	Refer to KSD2	Recharge high-voltage battery unit (to high-voltage charging socket)
And:		
61 33 550	Refer to KSD2	Replacing left fanfare
Or:		
61 33 555	Refer to KSD2	Replacing right fanfare
Or:		
61 33 560	Refer to KSD2	Replacing both two-tone horns

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowances.

[Copyright ©2016 BMW of North America, Inc.]