

Measure no.

US 62536917-01

Subject

Air duct on the lower triple clamp is missing

Status date (mm/dd/yy)

3/17/16

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

3/17/16

Created by

Christine Koehling

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K18/11

Engine**Body****Production period (from/to)
(mm/dd/yy)**

9/30/15 /

Comment on production periodSINCE series introduction of the
model revision**Feedback (all cases relating to
measure up to) (mm/dd/yy)****Complaint**

The air duct on the lower triple clamp is missing.

Cause

The air duct 46 63 7 725 148 is deleted for the C 650 Sport (K18/11).

Measure

Retrofitting of the air duct is not necessary and cannot be invoiced on warranty.

Complaint

	Fault location	Fault type	Fault place
†	46/63 Air supply at radiator	Missing, missing part: small part	

Cause

#	Fault location	Fault type	Fault place
† 1	46/63 Air supply at radiator		
	Repair Task	Special Clearance	Area

No action

No

Body and Trim

Fault code


Progman / DIS / ISTA / ISTA/P

System

State

Version

© 2002-2016 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.



291709