

**SUBJECT****ISTA/P Cannot Program an E-Series N55 Replacement DME****MODEL**

E70 (X50)

E71 (X6)

With the N55 engine and MEVD172 DME produced to 4/2012

E90 (3 Series Sedan)

E92 (3 Series Coupe)

E93 (3 Series Convertible)

With the N55 engine and MEVD172 DME produced to 3/2012

SITUATION

ISTA/P fails when attempting to program a replacement DME (MEVD172) on BN2000 E-Series vehicles with the Continental HPP.

Part number: 12 14 8 618 483.

CAUSE

DME logistic error between the replacement hardware and basic software prevents correct programming with ISTA/P.

CORRECTION

This will be corrected with the planned release of ISTA/P 3.59.3 (mid-August).

PROCEDURE**Note:****Until this ISTA/P version is available, an IRAP session should be setup to complete the DME replacement programming.**Please submit a PuMA case titled: **“IRAP – Program replacement N55 MEVD172 DME”****WARRANTY INFORMATION**

Not applicable.

[Copyright ©2016 BMW of North America, Inc.]