



SI B51 19 16
Body Equipment

June 2016
Technical Service

STEERING COLUMN STALK SWITCH STICKING

MODEL

| |
|----------|
| i12 (i8) |
|----------|

SITUATION

The steering column stalk switch for the turn signal sticks when actuating “headlight flasher” mode.

CAUSE


Interference fit between stalk switch and upper steering column shroud.

CORRECTION

Modify steering column shroud.

PROCEDURE

| |
|--|
| |
|--|







WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

| | | |
|---------------------|-----------------------|--|
| Defect Code: | 61 30 51 41 00 | |
|---------------------|-----------------------|--|

| | | |
|--|--|--|
| | | |
| | | |

| Labor Operation: | Labor Allowance: | Description: |
|-------------------------|-------------------------|--|
| 32 31 004 | Refer to KSD | Removing and installing or replacing upper steering column trim (Main work). |
| And: | | |
| 32 99 000 | 1 FRU | Work time to rework column trim |

If you are using a Main labor code for another repair, use the Plus code labor operation 32 31 504 instead.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowances.

Work time labor operation code 32 99 000 is not considered a Main labor operation. Also, since the “work time” FRU allowance to be claimed is specified, a separate punch time is not required.

[Copyright ©2016 BMW of North America, Inc.]