



Technical Journal

TITLE:

XC90 T8, Charge & Hold functions not availableREF NO:
TJ 31849.2.0ISSUING DEPARTMENT:
Technical ServiceCAR MARKET:
United States and CanadaPARTNER:
3 US 7510 Volvo Car USAISSUE DATE:
2016-11-28STATUS DATE:
2016-12-01FUNC GROUP:
3113FUNC DESC:
Battery, high voltage

Page 1 of 3

“Right first time in Time”

Attachment

File Name	File Size
Charge and hold.png	0.7645 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256	BC	B1BPHEV					2016-2017		0013986-0148236	201526-201646

CSC Customer Symptom Codes

Code	Description
YN	High voltage battery/Discharged/poor charge

VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

**DESCRIPTION:**

The driver may experience that Charge and Hold functions are not available and the icons have a yellow triangle and are grayed out.

See attached.

SERVICE:

Perform total upgrade according to TJ 31543.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 3113.

If software download fails, assure that the log-file from VIDA is included in the report, and also that you describe which step that failed.

To view TJ attachment continue to next page. This TJ has one attachment.

