VOLVO CAR SERVICE AND PARTS BUSINESS



Technical Journal

TITLE: Remote Control slider button now available as a spare part

REF NO: TJ 32004.1.0			CAR MARKET: United States and Canada	
3 US 7	PARTNER: 7510 Volvo Car USA	ISSUE DATE: 2016-11-30	STATUS DATE: 2016-12-07	
FUNC GROUP: 3669			1 of 4	

"Right first time in Time"

Attachment

File Name	File Size
TJI-497727_slider_button.pdf	0.4403 MB

Vehicle Type

Туре	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
234						2017-9999		0000350-99999999	201617-999952
256						2016-9999		0000561-99999999	201505-999952

CSC Customer Symptom Codes

Code	Description		
1J	Remote control/Mechanical problem/Key unit only		
XI	Remote control/Does not work		

VST Operation Number

VST Operation Number	Description
97073-2	Key slider install acc. to TJ

DTC Diagnostic Trouble Codes

Text

Technical Journal 32004.1.0



DESCRIPTION:

The Remote Control slider button is now available as a spare part. If the slider button is missing or damaged, there is no need to replace the entire remote control.

SERVICE:

Install a new slider button (31419983) according to the attached instruction.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support Not Needed", use function group 3669.

To view TJ attachment continue to next page. This TJ has one attachment.

VOLVO	Volvo Car Customer Service	TJ Instruction VC	C-497727-1
Title	Remote key slider	Page	1(4)
Action	Product fix	Operation number:	97073-2

Issue	Date	Reason
1	2016-11	New method

Affected vehicles

Model year	Model
2017, 2018	S90 (17-)
2016, 2017,	XC90 (16-)
2018	

Materials

Materials	Qty.	Part No.	Notes
Slider	1.0	31419983	





