



Technical Journal

TITLE:
Service Action S49792: Rear Axle Shafts

REF NO: TJ 32118.1.1	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2016-11-15	STATUS DATE: 2016-11-18
FUNC GROUP: 4600	FUNC DESC: Rear axle, drive shaft	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256							2016-2016	21	0036429-0051827	0-0

CSC Customer Symptom Codes

Code	Description
XW	Service/repair/Service action/Recall

VST Operation Number

VST Operation Number	Description
46602-2	Drive shaft ,rear, 2 sides remove -install/replacement

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

**DESCRIPTION:**

Volvo Car USA LLC and Volvo Car of Canada Ltd (Volvo) on behalf of Volvo Car Corporation, has decided to launch Service Campaign S49792 on certain model year 2016 XC90 vehicles.

Volvo has identified that certain vehicles may have been manufactured with axle shaft boots that are out of specification. This can result in water and dirt ingress into the axle shaft boot and grease leakage over time.

SERVICE:

The corrective action is to replace both rear axle shafts according to Volvo Information and Diagnostics for Aftersales (VIDA) VCC-370372-5.

VEHICLE REPORT:

N/A