

	GROUP Body	MODEL 2017 Sorento (UMA)
	NUMBER 138 (REV 1, 05/31/2016)	DATE May 2016
TECHNICAL SERVICE BULLETIN		
SUBJECT: SERVICE ACTION: "FE" EMBLEM INSTALLATION (SA230)		

*** NOTICE**

This bulletin has been revised to include additional information. New/revised sections of this bulletin are indicated by a black bar in the left margin area.

This bulletin provides the procedure to add an "FE" (Fuel Efficient) emblem to the existing "AWD" emblems on the front doors on specific 2017MY Sorento (UMa) vehicles, produced from April 1, 2016 to April 15, 2016. See VIN list on page 4.



*** NOTICE**

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service> Warranty Coverage> Warranty Coverage Inquiry> Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs> Not Completed Recall> Recall VIN> Select Report), which includes a list of affected vehicles.

This issue number is SA230.

File Under: Body

Circulate To: General Manager Service Manager Parts Manager
 Service Advisors Technicians Body Shop Manager Fleet Repair

Inspection:

1. Inspect the front doors for the presence of the 'FE' Emblem.
2. If the emblem is present, no further action is required.
3. If the emblem is not present, proceed to the procedure below.

Left Front Door

1. Remove and discard the "AWD" emblem from the foam guide of the replacement part, labeled LH.
2. Clean the door surface at the trailing edge of the AWD emblem, using isopropyl alcohol.
3. Carefully remove the "FE" emblem from the foam guide.
4. Position the foam guide over the existing "AWD" emblem as shown.
5. Remove backing from the "FE" emblem and position emblem in opening in foam and apply even pressure to the face of the "FE" emblem to adhere to the body using the foam guide.
6. Confirm proper alignment, and proceed to the right front door.



Drivers Side, "FE" after AWD

Right Front Door

1. Remove the "FE" emblem completely from the foam, and discard the guide, as it will not be used.
2. Clean the door surface at the trailing edge of the AWD emblem on the door, using isopropyl alcohol.
3. Align using a non-marring ruler under the "A" in the existing "AWD" emblem, as shown.
4. Remove the backing from the "FE" emblem and place the right side of the emblem 8mm (or 3/8 inch) from the "A" in AWD. Apply even pressure to the face of the emblem to adhere to the body.
5. Confirm proper alignment.



Passenger Side, "FE" before AWD

SUBJECT: SERVICE ACTION: "FE" EMBLEM INSTALLATION (SA230)

AFFECTED VEHICLE RANGE:

Model	Production Date Range
Sorento (UMa)	From April 1, 2016 thru April 15, 2016

REQUIRED PART:

Part Name	Model		
Emblem, AWD	Sorento (UMA)	86340 C6000	Left Side (LH)
		86340 C6100	Right Side (RH)

*** NOTICE**

For dealers with affected in-stock vehicle inventory, parts will be automatically shipped with respective quantity of parts to complete this Service Action. No part ordering required.

WARRANTY INFORMATION:

Claim Type	Causal P/N	Qty.	N Code	C Code	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
V	86340 C5100	0	N99	C99	(SA230) "FE" Emblem Inspection / Installation (Left and Right)	160A15R0	0.3	86340 C6000 86340 C6100	1 1

Note: LTS shows labor at 0.2 hr per emblem; since both sides are having a partial addition and no removal required, the labor time has been adjusted to 0.3 hr for both sides.

*** NOTICE**

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SA230 when accessing the WebDCS system.

SUBJECT: SERVICE ACTION: "FE" EMBLEM INSTALLATION (SA230)

AFFECTED VINS:

5XYPGDA50HG193283	5XYPHDA51HG188882	5XYPHDA55HG188089	5XYPHDA58HG190872
5XYPGDA50HG193994	5XYPHDA51HG189627	5XYPHDA55HG188433	5XYPHDA58HG193206
5XYPGDA51HG187511	5XYPHDA51HG190485	5XYPHDA55HG188450	5XYPHDA59HG185437
5XYPGDA51HG188190	5XYPHDA51HG190664	5XYPHDA55HG188500	5XYPHDA59HG187902
5XYPGDA52HG186223	5XYPHDA51HG190826	5XYPHDA55HG188688	5XYPHDA59HG187981
5XYPGDA52HG187467	5XYPHDA51HG191555	5XYPHDA55HG189548	5XYPHDA59HG188077
5XYPGDA52HG191955	5XYPHDA51HG192253	5XYPHDA55HG189579	5XYPHDA59HG188533
5XYPGDA53HG188627	5XYPHDA51HG193189	5XYPHDA55HG191722	5XYPHDA59HG188581
5XYPGDA53HG190412	5XYPHDA51HG193225	5XYPHDA55HG192501	5XYPHDA59HG188676
5XYPGDA54HG185901	5XYPHDA51HG193239	5XYPHDA55HG193230	5XYPHDA59HG188788
5XYPGDA54HG187437	5XYPHDA51HG193242	5XYPHDA55HG193387	5XYPHDA59HG189231
5XYPGDA54HG190113	5XYPHDA51HG193256	5XYPHDA56HG187436	5XYPHDA59HG189388
5XYPGDA54HG192217	5XYPHDA52HG187465	5XYPHDA56HG188134	5XYPHDA59HG189567
5XYPGDA55HG187494	5XYPHDA52HG187532	5XYPHDA56HG188604	5XYPHDA59HG189598
5XYPGDA55HG193988	5XYPHDA52HG187711	5XYPHDA56HG188652	5XYPHDA59HG189603
5XYPGDA55HG196745	5XYPHDA52HG188146	5XYPHDA56HG188845	5XYPHDA59HG189651
5XYPGDA56HG184989	5XYPHDA52HG188261	5XYPHDA56HG189090	5XYPHDA59HG189732
5XYPGDA56HG188430	5XYPHDA52HG188664	5XYPHDA56HG189235	5XYPHDA59HG190783
5XYPGDA56HG192946	5XYPHDA52HG188745	5XYPHDA56HG189591	5XYPHDA59HG190878
5XYPGDA57HG187545	5XYPHDA52HG188776	5XYPHDA56HG189929	5XYPHDA59HG193022
5XYPGDA57HG187674	5XYPHDA52HG189409	5XYPHDA56HG192815	5XYPHDA59HG193389
5XYPGDA57HG187741	5XYPHDA52HG189698	5XYPHDA56HG192832	5XYPHDA5XHG187830
5XYPGDA58HG192947	5XYPHDA52HG193248	5XYPHDA57HG187753	5XYPHDA5XHG187973
5XYPGDA59HG187420	5XYPHDA52HG193251	5XYPHDA57HG187946	5XYPHDA5XHG188699
5XYPGDA59HG187434	5XYPHDA53HG188379	5XYPHDA57HG188997	5XYPHDA5XHG189030
5XYPGDA59HG187742	5XYPHDA53HG188592	5XYPHDA57HG189227	5XYPHDA5XHG189156
5XYPGDA59HG187773	5XYPHDA53HG188639	5XYPHDA57HG189387	5XYPHDA5XHG189173
5XYPGDA5XHG186101	5XYPHDA53HG189189	5XYPHDA57HG189597	5XYPHDA5XHG189268
5XYPGDA5XHG187507	5XYPHDA53HG189547	5XYPHDA57HG190801	5XYPHDA5XHG189805
5XYPGDA5XHG190021	5XYPHDA53HG189595	5XYPHDA57HG190877	5XYPHDA5XHG190095
5XYPGDA5XHG191492	5XYPHDA53HG189600	5XYPHDA57HG191737	5XYPHDA5XHG193028
5XYPGDA5XHG196546	5XYPHDA53HG189743	5XYPHDA57HG192239	5XYPHDA5XHG193031
5XYPHDA50HG187755	5XYPHDA53HG190486	5XYPHDA57HG192287	
5XYPHDA50HG188100	5XYPHDA53HG193338	5XYPHDA57HG192774	
5XYPHDA50HG188470	5XYPHDA54HG187953	5XYPHDA57HG192788	
5XYPHDA50HG188761	5XYPHDA54HG188052	5XYPHDA57HG192841	
5XYPHDA50HG189005	5XYPHDA54HG188262	5XYPHDA57HG193018	
5XYPHDA50HG189506	5XYPHDA54HG188746	5XYPHDA57HG193200	
5XYPHDA50HG189554	5XYPHDA54HG189489	5XYPHDA57HG193388	
5XYPHDA50HG191496	5XYPHDA54HG190058	5XYPHDA58HG187454	
5XYPHDA50HG191563	5XYPHDA54HG190125	5XYPHDA58HG187700	
5XYPHDA50HG192230	5XYPHDA54HG191498	5XYPHDA58HG188295	
5XYPHDA50HG193233	5XYPHDA54HG191548	5XYPHDA58HG188751	
5XYPHDA51HG185366	5XYPHDA54HG192408	5XYPHDA58HG188944	
5XYPHDA51HG187974	5XYPHDA54HG192585	5XYPHDA58HG189267	
5XYPHDA51HG188123	5XYPHDA54HG193025	5XYPHDA58HG189494	
5XYPHDA51HG188557	5XYPHDA55HG187427	5XYPHDA58HG189530	