



A Toyota Group Company

## SERVICE BULLETIN INDEX

| Bulletin No. | Issue/Rev Date | Group Type                  | Description                                                                                         |
|--------------|----------------|-----------------------------|-----------------------------------------------------------------------------------------------------|
| SB-15-019    | 17-Jun-15      | Cab & Body                  | SB-15-019 11MY-15MY Conventional Cracked Hood Repair                                                |
| SB-14-020    | 22-Sep-14      | Cab & Body                  | SB-14-020 11MY-15MY Conventional Broken Hood Grille                                                 |
| SB-14-001    | 25-Aug-14      | Cab & Body                  | SB-14-001 COE Cab Step Cracked                                                                      |
| SB-13-014    | 10-Oct-13      | Cab & Body                  | SB-13-014 Seat Squeak                                                                               |
| SB-13-009    | 29-Jul-13      | Cab & Body                  | SB-13-009 2005 thru 2017 Paint Codes                                                                |
| SB-13-002    | 5-Jun-13       | Cab & Body                  | SB-13-002 2011 thru 2013 Radiator Grille ( <b>Superseded by SB-14-020</b> )                         |
| SB-12-003    | 27-Nov-12      | Cab & Body                  | SB-12-003 Keyless Fob Programming                                                                   |
| SB-08-005    | 31-Dec-08      | Cab & Body                  | SB-08-005 Hood Damper Shape Change                                                                  |
| SB-15-036    | 25-Sep-15      | Cooling                     | SB-15-036 Radiator Reservoir Tank Hose Replacement                                                  |
| SA-14-018    | 11-Sep-14      | Cooling                     | SA-14-018 DEF Becomes Mixed with Engine Coolant                                                     |
| SB-13-013    | 10-Oct-13      | Cooling                     | SB-13-013 Procedure for When DEF Mixed into coolant                                                 |
| SB-10-005    | 24-Nov-10      | Cooling                     | SB-10-005 Information of New Long Life Coolant (LL                                                  |
| SB-06-001    | 10-Jul-06      | Cooling                     | SB-06-001 Oil Cooler Housing Design Change                                                          |
| SB-05-009    | 4-Nov-05       | Cooling                     | SB-05-009 Upper Radiator Top Tank Design Change                                                     |
| SB-05-007    | 4-Nov-05       | Cooling                     | SB-05-007 Water pipe Design Change J08E                                                             |
| SB-14-025    | 5-Feb-15       | Electrical Systems & Meters | SB-14-025 11MY-14MY Junction Box Corrosion Due to Water Intrusion                                   |
| SB-13-003    | 29-Jul-13      | Electrical Systems & Meters | SB-13-003 Parking Brake Switch                                                                      |
| SB-10-002    | 23-Feb-10      | Electrical Systems & Meters | SB-10-002 Starter Assembly Mounting Nuts Torque Co                                                  |
| SB-10-001    | 23-Feb-10      | Electrical Systems & Meters | SB-10-001 Starter Assembly Mounting Nuts Torque Co                                                  |
| SB-05-004    | 13-Nov-06      | Electrical Systems & Meters | SB-05-004 Speedometer Recalibration                                                                 |
| SB-16-020    | 2-Aug-16       | Engine                      | SB-16-020 13MY-17MY COE DTC P0005, P20DE, P20DF                                                     |
| SB-16-019    | 2-Aug-16       | Engine                      | SB-16-019 15MY-17MY Conv. DTC P0005, P20DE, P20DF                                                   |
| SB-16-016    | 14-Jul-16      | Engine                      | SB-16-016 13MY-17MY COE DCU Software Update                                                         |
| SB-16-015    | 14-Jul-16      | Engine                      | SB-16-015 11MY-17MY Conventional DCU Software Update                                                |
| SB-16-012    | 28-Jun-16      | Engine                      | SB-16-012 17MY Conventional DTC P0300 False Detection                                               |
| SB-16-008    | 3-May-16       | Engine                      | SB-16-008 COE P0611 Engine ECU                                                                      |
| SB-16-007    | 3-May-16       | Engine                      | SB-16-007 Conventional P0611 Engine ECU                                                             |
| SB-16-002    | 11-Jan-16      | Engine                      | SB-16-002 15MY-16MY DCU Update for NOX Sensor ( <b>Supersedes SB-15-038</b> )                       |
| SB-15-038    | 17-Nov-15      | Engine                      | SB-15-038 15MY-16MY DCU Update for NOX Sensor                                                       |
| SB-15-026    | 2-Jun-15       | Engine                      | SB-15-026 05MY-15MY J08 Engine Cylinder Head Gasket                                                 |
| SB-15-025    | 6-Jul-15       | Engine                      | SB-15-025 16MY COE False P0128 Detection                                                            |
| SB-15-023    | 13-Apr-15      | Engine                      | SB-15-023 16MY P2148, P2151, P026C, P026D ECU Software Enhancement                                  |
| SB-14-014    | 25-Jul-14      | Engine                      | SB-14-014 11MY-14MY BCU Reprogramming ( <b>Superseded by Campaign #AA0M0</b> )                      |
| SB-14-013    | 23-Jul-14      | Engine                      | 11MY-14MY Conventional Truck – ECU Software Enhancement                                             |
| SB-14-012    | 15-Jul-14      | Engine                      | 15MY Conventional Truck – False P0421 DTC Setting in the Engine ECU ( <b>Supersedes TT-14-014</b> ) |
| SB-14-007    | 2-Jul-14       | Engine                      | SB-14-007 Inspection Procedure for Auto Regeneration                                                |
| SB-14-004    | 17-Jun-14      | Engine                      | SB-14-004 14MY Conventional Truck – Manual Transmission                                             |
| SB-13-008    | 29-Jul-13      | Engine                      | SB-13-008 Design Change Idler Gear Case and Bolt                                                    |
| SB-08-001    | 2-Jun-08       | Engine                      | SB-08-001 Crankcase Breather Anti Freezing Kit                                                      |
| SB-07-005    | 24-Apr-07      | Engine                      | SB-07-005 Rocker Arm Bolt Material & Torque Change                                                  |
| SB-07-001    | 12-Jan-07      | Engine                      | SB-07-001 Flywheel Aligning Mark Change                                                             |
| SB-07-002    | 12-Feb-07      | Front Axle                  | SB-07-002 Outer Wheel Bearing Nut Torque Reduction                                                  |
| SB-05-005    | 27-Oct-10      | Front Axle                  | SB-05-005 Wheel Bearing Repack and Adjustment                                                       |
| SB-14-010    | 8-Jul-14       | Fuel Systems                | SB-14-010 2012MY-14MY COE FUEL TANK BREATHER CLOGG                                                  |
| SB-11-002    | 10-Aug-11      | Fuel Systems                | SB-11-002 Requirements of BioFuel for 2008 thr                                                      |
| SB-10-003    | 27-Oct-10      | Fuel Systems                | SB-10-003 Fuel Filter Usage 2005 thru 2011                                                          |
| SB-09-002    | 15-Jun-09      | Fuel Systems                | SB-09-002 Supply Pump Suction Control Valve J05                                                     |
| SB-09-001    | 15-Jun-09      | Fuel Systems                | SB-09-001 Supply Pump Suction Control Valve J08                                                     |
| SB-08-004    | 28-Aug-08      | Fuel Systems                | SB-08-004 Design Change of Supply Pump for SCV                                                      |
| SB-08-003    | 28-Aug-08      | Fuel Systems                | SB-08-003 Addition of Fuel Pipes to Davco Fuel Fil                                                  |
| SB-07-006    | 24-Apr-07      | Fuel Systems                | SB-07-006 Suction Control Valve/Fuel Supply Pump                                                    |
| SB-06-002    | 18-Sep-06      | Fuel Systems                | SB-06-002 Fuel Filter Usage                                                                         |



A Toyota Group Company

## SERVICE BULLETIN INDEX

| Bulletin No. | Issue/Rev Date | Group Type             | Description                                                                    |
|--------------|----------------|------------------------|--------------------------------------------------------------------------------|
| SB-05-008    | 4-Nov-05       | Fuel Systems           | SB-05-008 Common Rail Pressure Sensor Cover                                    |
| SB-16-026    | 5-Oct-16       | General                | SB-16-026 13MY-17MY COE Hybrid Motor Service Alert                             |
| SB-16-024    | 18-Aug-16      | General                | SA-16-024 Burner Atomizer Repair Service Alert                                 |
| SA-16-023    | 23-Sep-16      | General                | SA-16-023 DEF Injector Assembly Service Alert                                  |
| SB-16-022    | 16-Aug-16      | General                | SB-16-022 11MY-14MY Conv. Burner Atomizer Repair Procedure                     |
| SB-16-018    | 15-Jul-16      | General                | SB-16-018 13MY-17MY COE VCS Software Update                                    |
| SB-16-017    | 14-Jul-16      | General                | SB-16-017 EGR Valve Reprogram Kit                                              |
| SA-16-014    | 6-Jul-16       | General                | SA-16-014 PM Sensor Software Delete Service Alert                              |
| SA-16-013    | 6-Jul-16       | General                | SA-16-013 16MY-17MY Conventional Air Brake Drag Service Alert                  |
| SA-16-011    | 20-Jun-16      | General                | SA-16-011 AA2M0 and AA2N0 Recall Suspension                                    |
| SB-15-048    | 11-Apr-16      | General                | SB-15-048 DPF Bracket Corrosion                                                |
| SA-15-047    | 4-Dec-15       | General                | SA-15-047 P142A DEF Code                                                       |
| SB-15-035    | 22-Sep-15      | General                | SB-15-035 13MY-16MY COE Loose or Missing Seat Bolt                             |
| SB-15-031    | 26-Aug-15      | General                | SB-15-031 Strainer for DEF Tank Filler Inlet                                   |
| SB-15-030    | 7-Jul-15       | General                | SB-15-030 14MY-15MY DTC U02A2 DEF Sensor Error                                 |
| SB-15-010    | 26-Jan-15      | General                | SB-15-010 11MY-15MY EGR Valve Heater Procedure                                 |
| SB-15-009    | 26-Jan-15      | General                | SB-15-009 05MY-08MY Allison Vent Tube                                          |
| SA-14-024    | 8-Oct-14       | General                | SA-14-024 15MY DTC P2080 and P2084                                             |
| SA-14-023    | 8-Oct-14       | General                | SA-14-023 PDI Worksheets Coolant Update                                        |
| SA-14-021    | 23-Sep-14      | General                | SA-14-021 DEF Nozzle and Side Fuel Tank Inspection                             |
| SA-14-015    | 8-Sep-14       | General                | SB-14-015 1K-3K Fluid Change Intervals                                         |
| SB-14-009    | 8-Jul-14       | General                | SB-14-009 2011MY-12MY Crossmember Loose or Missing                             |
| SB-14-008    | 3-Jul-14       | General                | SB-14-008 COE HYBRID SAFETY EQUIPMENT, TOOLS AND P                             |
| SB-14-006    | 1-May-14       | General                | SB-14-006 P1604 DTC 2013-2015MY COE Diesel Hybrid                              |
| SB-14-005    | 19-Jun-14      | General                | SB-14-005 2011-2015MY Conventional Keyless Entry P                             |
| SB-11-004    | 8-Nov-11       | General                | SB-11-004 HD OBD Specification Table                                           |
| SB-07-007    | 14-Oct-07      | General                | SB-07-007 Diagnostic Explorer 1.2.0                                            |
| SB-15-017    | 6-Mar-15       | Intake & Exhaust       | SB-15-017 08MY-10MY J05 Broken Exhaust Manifold Stud<br>(Supersedes TT-11-001) |
| SB-15-016    | 6-Mar-15       | Intake & Exhaust       | SB-15-016 13MY-15MY J05 Broken Exhaust Manifold Stud                           |
| SB-12-002    | 4-Oct-12       | Intake & Exhaust       | SB-12-002 Flame Temperature Sensor Replacement Guidelines                      |
| SB-11-005    | 22-Nov-11      | Intake & Exhaust       | SB-11-005 DEF Breather Hose Checking and Cleaning                              |
| SB-11-001    | 21-Jul-11      | Intake & Exhaust       | SB-11-001 Exhaust Manifold Stud Modification J05                               |
| SB-10-004    | 24-Nov-10      | Intake & Exhaust       | SB-10-004 Apply Grease to VNT Turbocharger Link Ro                             |
| SB-09-003    | 10-Jun-09      | Intake & Exhaust       | SB-09-003 Intake Throttle Service Bulletin                                     |
| SB-08-002    | 28-Aug-08      | Intake & Exhaust       | SB-08-002 Design Change to EGR Valve and Gasket                                |
| SB-05-003    | 27-Sep-05      | Intake & Exhaust       | SB-05-003 Exhaust Brake Activation Instructions                                |
| SB-05-006    | 27-Oct-10      | Meters                 | SB-05-006 Aisin Installation Caution                                           |
| SB-13-001    | 30-Apr-13      | Rear Axle              | SB-13-001 Incorrect Rear Axle Differential Fluid                               |
| SB-07-003    | 12-Feb-07      | Rear Axle              | SB-07-003 Redesigned Axle Breather                                             |
| SB-16-031    | 9-Nov-16       | Service Manual Updates | SB-16-031 P20DF Workshop Manual Correction                                     |
| SB-16-030    | 9-Nov-16       | Service Manual Updates | SB-16-030 P20DE Workshop Manual Correction                                     |
| SB-16-029    | 9-Nov-16       | Service Manual Updates | SB-16-029 Fuel Pipe Installation Workshop Manual Correction                    |
| SB-16-028    | 19-Oct-16      | Service Manual Updates | SB-16-028 J05C Rocker Arm Bolt Torque Change Workshop Manual                   |
| SB-16-027    | 19-Oct-16      | Service Manual Updates | SB-16-027 J08E Rocker Arm Bolt Torque Change Workshop Manual                   |
| SB-16-025    | 9-Sep-16       | Service Manual Updates | SB-16-025 Clutch Learning Workshop Manual Correction                           |
| SB-16-021    | 5-Aug-16       | Service Manual Updates | SB-16-021 Electrical Diagram Workshop Manual Correction                        |
| SB-16-010    | 18-Apr-16      | Service Manual Updates | SB-16-010 DPR Filter Inspection Workshop Manual Correction                     |
| SB-16-009    | 11-Apr-16      | Service Manual Updates | SB-16-009 Electrical Diagram Workshop Manual Correction                        |
| SB-16-005    | 4-Mar-16       | Service Manual Updates | SB-16-005 Fuel Pipe Installation Workshop Manual Correction                    |
| SB-16-004    | 4-Mar-16       | Service Manual Updates | SB-16-004 Clutch Learning Workshop Manual Correction                           |
| SB-16-001    | 8-Jan-16       | Service Manual Updates | SB-16-001 COE Front Leaf Spring Workshop Manual Correction                     |
| SB-15-044    | 19-Nov-15      | Service Manual Updates | SB-15-044 P2214 Workshop Manual Correction                                     |
| SB-15-043    | 19-Nov-15      | Service Manual Updates | SB-15-043 P2201 Workshop Manual Correction                                     |
| SB-15-042    | 19-Nov-15      | Service Manual Updates | SB-15-042 P206B Workshop Manual Correction                                     |
| SB-15-041    | 19-Nov-15      | Service Manual Updates | SB-15-041 P20EE Workshop Manual Correction                                     |
| SB-15-040    | 19-Nov-15      | Service Manual Updates | SB-15-040 P207F Workshop Manual Correction                                     |
| SB-15-039    | 19-Nov-15      | Service Manual Updates | SB-15-039 Nox Sensor Workshop Manual Correction                                |
| SB-15-037    | 5-Nov-15       | Service Manual Updates | SB-15-037 Cam Height Workshop Manual Correction                                |
| SB-15-034    | 12-Aug-15      | Service Manual Updates | SB-15-034 DTC P0A84 Workshop Manual Correction                                 |
| SB-15-033    | 12-Aug-15      | Service Manual Updates | SB-15-033 Addition of Brake Master Cylinder Workshop Manual                    |
| SB-15-032    | 21-Oct-15      | Service Manual Updates | SB-15-032 P2030 Service Manual Correction                                      |



A Toyota Group Company

## SERVICE BULLETIN INDEX

| Bulletin No. | Issue/Rev Date | Group Type             | Description                                                                |
|--------------|----------------|------------------------|----------------------------------------------------------------------------|
| SB-15-029    | 22-Jun-15      | Service Manual Updates | SB-15-029 Correction of 300 Series Clutch Inspection                       |
| SB-15-027    | 5-Jun-15       | Service Manual Updates | SB-15-027 Revision of 300 Series Automatic Transmission                    |
| SB-15-021    | 23-Mar-15      | Service Manual Updates | SB-15-021 Correction of P20BD, P20B9 and P20C1 Workshop Manual             |
| SB-15-020    | 6-Mar-15       | Service Manual Updates | SB-15-020 Correction of DTC P0A78 Workshop Manual                          |
| SB-15-018    | 18-Feb-15      | Service Manual Updates | SB-15-018 Correction of Parking Brake Lever Assembly                       |
| SB-15-015    | 12-Feb-15      | Service Manual Updates | SB-15-015 Addition for Lack of Power During DPR Auto Regen                 |
| SB-15-007    | 16-Jan-15      | Service Manual Updates | SB-15-007 Manual Update for Addition of speedometer gear and cover (MZZ6F) |
| SB-15-006    | 16-Jan-15      | Service Manual Updates | SB-15-006 Manual Update for Addition of speedometer gear and cover (MYY6S) |
| SB-15-005    | 16-Jan-15      | Service Manual Updates | SB-15-005 Manual Update for Addition of speedometer hole cover (MYY5A)     |
| SB-15-004    | 16-Jan-15      | Service Manual Updates | SB-15-004 Manual Update for Addition of Engine SST                         |
| SB-15-003    | 16-Jan-15      | Service Manual Updates | SB-15-003 Manual Update for P0421 Procedure                                |
| SB-15-002    | 16-Jan-15      | Service Manual Updates | SB-15-002 Manual Update for P2123 Procedure                                |
| SB-15-001    | 16-Jan-15      | Service Manual Updates | SB-15-001 Manual Update for P0705 Procedure                                |
| SB-14-029    | 5-Dec-14       | Service Manual Updates | SB-14-029 Revision of DTC P2201 & P2214 Troubleshooting Procedure          |
| SB-14-028    | 5-Dec-14       | Service Manual Updates | SB-14-028 Revision of DTC P207F Troubleshooting Procedure                  |
| SB-14-003    | 7-Apr-14       | Service Manual Updates | SB-14-003 Revision of Inspection Procedure for DTC                         |
| SB-14-002    | 7-Apr-14       | Service Manual Updates | SB-14-002 Revision of Troubleshooting Procedure fo                         |
| SB-13-012    | 10-Oct-13      | Service Manual Updates | SB-13-012 Manual Correction 2013 155h 195h Wiring                          |
| SB-13-011    | 29-Jul-13      | Service Manual Updates | SB-13-011 Manual Correction COE DTC U0293                                  |
| SB-13-010    | 29-Jul-13      | Service Manual Updates | SB-13-010 Manual Correction DTC P204F                                      |
| SB-13-007    | 29-Jul-13      | Service Manual Updates | SB-13-007 Manual Correct. DEF Contamination Fillin                         |
| SB-13-006    | 29-Jul-13      | Service Manual Updates | SB-13-006 Manual Correction CAN Diagnostic Procedu                         |
| SB-13-005    | 29-Jul-13      | Service Manual Updates | SB-13-005 Manual Correction DPR and DEF Filter Mai                         |
| SB-13-004    | 29-Jul-13      | Service Manual Updates | SB-13-004 Correction of Manual COE DTC P2122, 2123                         |
| SB-12-004    | 15-Nov-12      | Service Manual Updates | SB-12-004 Workshop Manual Change 13MY (COE)                                |
| SB-12-001    | 9-Apr-12       | Service Manual Updates | SB-12-001 DEF Injector Torque (Addition to Manual)                         |
| SB-07-008    | 29-Nov-07      | Service Manual Updates | SB-07-008 Correction to Workshop Manual Injector C                         |
| SB-05-011    | 20-Nov-05      | Service Manual Updates | SB-05-011 Correction to Workshop Manual Piston Rin                         |
| SB-05-010    | 13-Nov-06      | Service Manual Updates | SB-05-010 Manual Corrections (Air Intake Relay)                            |
| SB-16-006    | 20-Apr-16      | Suspension             | SB-16-006 Conventional Rear Spring Pad Loose                               |
| SB-15-046    | 23-Nov-15      | Suspension             | SB-15-046 Conventional Front Spring Hanger Bolt Modification               |
| SB-15-028    | 16-Jun-15      | Suspension             | SB-15-028 12MY-16MY COE Stability Upgrade                                  |
| SB-15-022    | 19-Mar-15      | Suspension             | SB-15-022 23K HD Comfort Ride Conversion                                   |
| SB-14-011    | 15-Jul-14      | Suspension             | 2013MY-15MY COE Hybrid Cab Leaning to the Driver's Side                    |
| SB-16-034    | 17-Nov-16      | Brakes                 | SB-16-034 COE Hydroboost Reservoir Fluid Overflow or Aeration              |
| SA-16-003    | 19-Jan-16      | Brakes                 | SA-16-003 Air Parking Brake Valve Diagnosis and Replacement                |
| SB-14-017    | 8-Sep-14       | Brakes                 | 2008MY-10MY Allison Torque Converter Modification                          |
| SB-14-016    | 8-Sep-14       | Brakes                 | 2011MY-14MY Allison Torque Converter Modification                          |
| SB-14-019    | 16-Sep-14      | Brakes                 | 2005MY-07MY Allison Torque Converter Modification                          |
| SB-15-011    | 4-Feb-15       | Steering               | 12MY-15MY COE Steering Gear Adjustment Procedure                           |