



Technical Information Bulletin

E148



Section

Fuel

Subject

PACCAR MX Engine Fuel System Priming Videos

Release Date

7/14/2016

Condition

Vehicle fuel system requires bleeding after repair or servicing.

Chassis Affected

All Chassis with a PACCAR MX engine installed.

Action

INFORMATION ONLY

Review the instructional videos before using the Mity-Vac or DAVCO Fuel Pro tool to bleed the PACCAR MX Engine fuel system. See Procedure Section below.

Procedure

Instructional videos for this procedure can be found on the [BCA Kenworth Training Site](#). After logging in, follow the link below.

Service Videos

- Priming EPA2010 MX Engine with DAVCO Shop-Pro
 - Priming EPA2013 Engine with Mity-Vac 7430
 - Priming EPA2013 MX with DAVCO Shop-Pro
 - Priming MX13 EPA 2010 Engine with Mity-Vac 7430
-

Authored by: JS

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2016 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).