


Multi-Model - Rattle Noise From Rear of Vehicle (update)

Some customers may complain about a rattle type noise coming from the rear of the vehicle. The noise is similar to a loose liftgate latch. This may be caused by rocks (road debris) in the rear lower control Arm.



Remove the rocks to resolve rattle noise concern.

An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication. © 2016 Mazda Motor of America, Inc.

To contribute repair tip ideas, send an e-mail to mtips@mazdausa.com. If we select your repair tip, you will receive \$50 value in Reward Performance by Mazda (RPM) points for your efforts. All contributions become property of MNAO, which assumes permission to publish them without further consideration.