


# 2016 CX-9 - Exterior Side Garnish Damage Due To Improper Vehicle Lift

When lifting a CX-9 vehicle, adjust the height of the vehicle lift extension pad to prevent lift arm contact with the exterior side garnish. If not adjusted properly, the exterior side garnish and/or a fender may be damaged by the vehicle lift arm.



An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication. © 2016 Mazda Motor of America, Inc.

To contribute repair tip ideas, send an e-mail to [mtips@mazdausa.com](mailto:mtips@mazdausa.com). If we select your repair tip, you will receive \$50 value in Reward Performance by Mazda (RPM) points for your efforts. All contributions become property of MNAO, which assumes permission to publish them without further consideration.