

2016 CX-9 Tech Tips

- [2016 CX-9 - EXTERIOR SIDE GARNISH DAMAGE DUE TO IMPROPER VEHICLE LIFT](#)
- [2016 CX-9 - THIRD ROW SEAT HEAD RESTRAINT IS NOT UPRIGHT](#)
- [2016 CX-9 - REAR SUN SHADE WILL NOT RETRACT](#)
- [2016 CX-9 - MAINTENANCE MONITOR ENGINE OIL DATA RESET](#)
- [2016 CX-9 - ENHANCED PDI STEP 1](#)
- [2016 CX-9 - DO NOT UPDATE THE MAZDA CONNECT SOFTWARE](#)
- [2016 CX-9 - SPECIAL ATTENTION ITEMS TO REVIEW DURING PDI](#)
- [2016 CX-9 - DRIVEABILITY CONCERNS DUE TO LOW FUEL LEVEL](#)
- [2016 CX-9 - POWER LIFTGATE \(PLG\) OPERATION](#)
- [2016 CX-9 \(EQUIPPED WITH POWER LIFTGATE\) - POWER LIFTGATE INOPERATIVE WITH DTC U3003:16](#)
- [2016 CX-9 \(EQUIPPED WITH POWER LIFTGATE\) - POWER LIFTGATE CONTACTS GARAGE CEILING](#)

