

Service Alert No: 001313

Title: 2016 CX-9 - 2ND ROW SEAT WALK-IN AND RECLINE LEVER USAGE

**CAUTION: Do not operate the "Walk-in" lever AND the "Recline" lever at the same time.**

#### Walk-in Lever



#### Recline Lever



**Operating both at the same time will cause an excessive load on the walk-in lever bracket (shown below) at the release linkage. This can cause the bracket to bend downwards and reduce the operation of the walk-in lever.**

