

Service Alert No: 001317

Title: 2016 CX-9 - EXTERIOR SIDE GARNISH DAMAGE DUE TO IMPROPER VEHICLE LIFT

When lifting a CX-9 vehicle, adjust the height of the vehicle lift extension pad to prevent lift arm contact with the exterior side garnish. If not adjusted properly, the exterior side garnish and/or a fender may be damaged by the vehicle lift arm.

