



Parts Bulletin

TITLE:

**Service Action S39810: ABS Wiring
Model Year 2017 S90**

GROUP: 37	CAT/NO: S39810	REFERENCE BULLETINS: QB: S39810, TJ: 32069	CAR MARKET: United States and Canada	
COPY TO / CIRCULATIONS (PLEASE INITIAL):			ISSUE DATE: 2016-11-08	STATUS DATE: 2016-11-08
GENERAL MANAGER	PARTS MANAGER	SERVICE MANAGER	SALES MANAGER	
				Page 1 of 1

“Right first time in Time”

Reference Bulletins: QB: S39810, TJ: 32069

Volvo Car USA LLC and Volvo Car of Canada Ltd (Volvo) on behalf of Volvo Car Corporation, has decided to launch Service Action S39810 on certain model year 2017 S90 vehicles.

Volvo has identified that the Anti-Lock Brake System (ABS) wiring may chafe against the front drive-shaft bellow. This condition will light a yellow Electronic Stability Control, (ESC) and red (ABS) warning lamp, and a text message “ABS/ESC temporarily off” will appear in the instrument panel. If the fault is detected as permanent, a message “Brake system service required” will be also appear in the instrument panel.

The corrective action is to check and if necessary adjust the ABS wiring per Technical Journal 32069.

Service Action S39810 affects 1,441 vehicles in the U.S. and 87 in Canada.

The following part numbers apply:

Part Number	Description	Qty
983750	Cable Tie	2