



Tech Article

TA0006: Instrument Gauge Display Streaking

Reference	TA0006
Last Modified	January 27, 2016
Models	<i>2014 and later vehicles:</i>
Markets	Global
Category	Electrical
Symptoms	Streaking appearance or film residue on the inside of instrumentation gauges.

Description

See Figure 1. Harley-Davidson is aware of conditions that may result in a streaking appearance or film residue on the inside of some instrument gauges including speedometer and tachometers. This may occur after exposure of the vehicle to humid conditions. This condition may remain even after the moisture has evaporated.

Action

While this condition is warrantable, there is a high probability that the replacement part will exhibit the same condition at this time. Consider this when reviewing the issue and possible repairs to any affected vehicles. Harley-Davidson is aware of the condition and working toward a resolution.




Figure 1. Speedometer Streaking