



NEW FLYER®

3 March 2016

VIA EMAIL

Office of Compliance and Enforcement
National Highway Traffic Safety Administration (NHTSA)
1200 New Jersey Ave. SE,
Washington, DC 20590

Subject: **Sec. 579.5 - Notices, bulletins, customer satisfaction campaigns, consumer advisories, and other communications.**

To whom it may concern:

In accordance with provisions of the National Traffic and Motor Vehicle Safety Act of 1966, as amended, and associated regulations, New Flyer of America Inc. and New Flyer Industries Canada ULC (together, "New Flyer") herewith furnishes a representative copy of any maintenance notification which has been distributed to more than one dealer, owner and/or purchaser (transit authority) during the same calendar month.

Four Instructions to Service (ITS), one Parts Manual Bulletin (PMB), four Service Manual Bulletins (SMB) and one Technical Service Information Bulletin (TSIB) were released to more than one customer for the month of February 2016.

If you have any questions, please contact me at (204) 224-6706.

Sincerely,
NEW FLYER OF AMERICA INC.
NEW FLYER INDUSTRIES CANADA ULC

By: Kerry Legg
Vehicle Safety & Regulatory Compliance Manager
(204) 224-6706

Attachments: (See listing - next page)

Headquarters/
Winnipeg Facility
711 Kernaghan Ave.
Winnipeg, Manitoba
R2C 3T4 Canada
Ph: (204) 224-1251

Aftermarket Facility
630 Kernaghan Ave.
Door 76
Winnipeg, Manitoba
R2C 5G1 Canada
Ph: (204) 982-8400

New Product
Development
630 Kernaghan Ave.
Winnipeg, Manitoba
R2C 5G1 Canada
Ph: (204) 982-8400

Crookston
Facility
214 5th Ave. SW
Crookston, Minnesota
56716 USA
Ph: (218) 281-5752

St. Cloud
Facility
6200 Glenn Carlson Dr.
St. Cloud, Minnesota
56301 USA
Ph: (320) 203-0576

Anniston
Facility
106 National Drive
Anniston, AL
36207 USA
Ph: (256) 831-4296

Built to
RELY ON.™
www.newflyer.com

- ITS6137 Retrofit Acorn Nuts on Modesty Panels. This instruction is applicable to specifically equipped 2014-15 MD30 and 2014-15 MD35 model buses.
- ITS6167 Rotate Current Sensor. This instruction effects specifically equipped 2015 XD60 and 2013-16 XDE40 model buses.
- ITS6182 Remove and Reinstall Driver's Barrier with Loctite. This instruction is applicable to specifically equipped 2014 XT60, 2015 XN40, 2015-16 XDE60 and 2016 XDE40 model buses.
- ITS6192 Retrofit PPV Valve to Emergency Brake Release System. This instruction is applicable to specifically equipped 2013 XD40 and 2015 XN40 model buses in New York State.
- PMB045 Steering System Adjustment Tools. This bulletin effects all Xcelsior and Low Floor model buses.
- SMB138B Steering System Adjustment. This bulletin is applicable to all Xcelsior, Low Floor and Invero model buses.
- SMB141B Steering Knuckle Lubrication. This bulletin is applicable to all Xcelsior, Low Floor and Invero model buses.
- SMB153 Battery Jump Charging/Starting. This bulletin effects specifically all Diesel, CNG/LNG and Fuel cell models of bus.
- SMB154 Air System Governor Adjustment for California. This bulletin is applicable to all Xcelsior and Low Floor model buses in the State of California.
- TSIB1507 Alternator Power Cable Support Inspections. This bulletin effects all Xcelsior and Low Floor model buses.