



NEW FLYER®

6 April 2016

VIA EMAIL

Office of Compliance and Enforcement
National Highway Traffic Safety Administration (NHTSA)
1200 New Jersey Ave. SE,
Washington, DC 20590

Subject: **Sec. 579.5 - Notices, bulletins, customer satisfaction campaigns,
consumer advisories, and other communications.**

To whom it may concern:

In accordance with provisions of the National Traffic and Motor Vehicle Safety Act of 1966, as amended, and associated regulations, New Flyer of America Inc. and New Flyer Industries Canada ULC (together, "New Flyer") herewith furnishes a representative copy of any maintenance notification which has been distributed to more than one dealer, owner and/or purchaser (transit authority) during the same calendar month.

Four Instructions to Service (ITS) were released to more than one customer for the month of March 2016.

If you have any questions, please contact me at (204) 224-6706.

Sincerely,
NEW FLYER OF AMERICA INC.
NEW FLYER INDUSTRIES CANADA ULC

By: Kerry Legg
Vehicle Safety & Regulatory Compliance Manager
(204) 224-6706

Attachments: (See listing - next page)

Headquarters/
Winnipeg Facility
711 Kernaghan Ave.
Winnipeg, Manitoba
R2C 3T4 Canada
Ph: (204) 224-1251

Aftermarket Facility
630 Kernaghan Ave.
Door 76
Winnipeg, Manitoba
R2C 5G1 Canada
Ph: (204) 982-8400

New Product
Development
630 Kernaghan Ave.
Winnipeg, Manitoba
R2C 5G1 Canada
Ph: (204) 982-8400

Crookston
Facility
214 5th Ave. SW
Crookston, Minnesota
56716 USA
Ph: (218) 281-5752

St. Cloud
Facility
6200 Glenn Carlson Dr.
St. Cloud, Minnesota
56301 USA
Ph: (320) 203-0576

Anniston
Facility
106 National Drive
Anniston, AL
36207 USA
Ph: (256) 831-4296

Built to
RELY ON.™
www.newflyer.com

- ITS6164 Replace surge tank low coolant level sensor. This instruction is applicable to specifically equipped 2013 XN35 and 2013-15 XN40 model buses.
- ITS6185 Inspect Streetside Exterior Mirror Snap Bushing. This instruction effects specifically equipped 2015 XD35, 2015 XD60, 2014-15 XDE60, 2014-15 XN40, 2015 XN60 and 2014 XT60 model buses.
- ITS6215 Clean Traction Motor Ground Connection. This instruction is applicable to specifically equipped 2014-15 XT40 and 2014-15 XT60 model buses.
- ITS6216 Remove and Replace Defroster Heater Blower Resistor. This instruction is applicable to specifically equipped 2014-15 XD40, 2014-15 XD60, 2014 XDE35, 2014-15 XDE40, 2014 XDE60, 2013-14 XN35, 2013-14 XN40 and 2014 XN60 model buses.