



TECHNICAL SERVICE BULLETIN

TSB#: 16-028

Job Code: 9903336

.6 Hr TSB 13

Inspection of sway bar orientation and frame bracket replacement

1.0 Hr TSB 14

Changing sway bar orientation and frame bracket replacement

Date of Publication:

November 2016

Action Required

Inspect sway bar for proper orientation and flip when required
Replace frame bracket

Affected Units

2017 Precept Motorhomes

H1UL0051-0210

H1US0051-0110

H1UP0051-0061

Parts Kit 16-028JM

Note: Kit can only be ordered using the order form included with this bulletin.

1 Hellwig Frame Bracket Service Kit (7904)

Please refer to LCI TSB 02-001-16A attached for Repair Instructions.