

March 16, 2016

03182 Version 1

## Driver's Seat Bottom Cover Material Looks Unfinished

### AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2015	CR-V	EX, EX-L, Touring	ALL
2016	CR-V 2WD	EX, EX-L, Touring	2HKRM3...GH500001 thru 2HKRM3...GH512177
			5J6RM3...GL000001 thru 5J6RM3...GL004319
2016	CR-V AWD	EX, EX-L, Touring	2HKRM4...GH600001 thru 2HKRM4...GH627160
			5J6RM4...GL000001 thru 5J6RM4...GL023330

### BACKGROUND

The driver's seat bottom cover is not hemmed and appears unfinished. This bulletin should only be completed for customer complaints.

### POSSIBLE CAUSE

The right side of the driver's seat bottom cover is not hemmed by design.

### CORRECTIVE ACTION

Replace the seat cover.

### PARTS INFORMATION

Part Name	Year/Trim	Color Code	Part Number	Quantity
Left Front Seat Cushion Cover	2015 EX	YR449L (Cashmere Ivory)	81531-T0G-A61ZA	1
	2015 EX	NH836L (Wisteria Light Gray)	81531-T0G-A61ZB	1
	2015 EX	NH167L (Graphite Black)	81531-T0G-A61ZC	1
	2016 EX	YR449L (Cashmere Ivory)	81531-T0G-A63ZA	1
	2016 EX	NH836L (Wisteria Light Gray)	81531-T0G-A63ZB	1
	2016 EX	NH167L (Graphite Black)	81531-T0G-A63ZC	1
	2015-16 EX-L	NH167L (Graphite Black)	81531-T0G-L83ZC	1
	2015-16 EX-L	NH836L (Wisteria Light Gray)	81531-T0G-L83ZE	1
	2015-16 EX-L	YR449L (Cashmere Ivory)	81531-T0G-L83ZF	1
	2015-16 Touring	NH167L (Graphite Black)	81531-T0G-L92ZA	1
	2015-16 Touring	YR449L (Cashmere Ivory)	81531-T0G-L92ZB	1
	2015-16 Touring	NH836L (Wisteria Light Gray)	81531-T0G-L92ZC	1

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

## REQUIRED MATERIALS

Part Name	Part Number	Quantity
C-Clip Set (30 clips per set. Each repair requires 9 clips. One set covers 3 repairs.)	04810-SB3-000	1

## REQUIRED TOOLS

Part Name	Part Number	Quantity
Upholstery Ring Pliers	Commercially available	1

## WARRANTY CLAIM INFORMATION

The normal warranty applies.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Trim/Color	Template ID	Failed Part Number
8591A0	Replace the seat cover.	1.1 hr	07404	00101	EX (Cashmere Ivory)	16-015A	81531-T0G-L82ZC
					EX (Wisteria Light Gray)	16-015B	
					EX (Graphite Black)	16-015C	
					EX-L (Graphite Black)	16-015D	
					EX-L (Cashmere Ivory)	16-015E	
					EX-L (Wisteria Light Gray)	16-015F	
					Touring (Graphite Black)	16-015G	
					Touring (Cashmere Ivory)	16-015H	
					Touring (Wisteria Light Gray)	16-015J	

Skill Level: Repair Technician

## REPAIR PROCEDURE

Replace the front left seat cushion cover. Refer to the service information.

END