

Fault code U012100, U014600 after software update for transmission control unit

Topic number	LI27.60-P-064637
Version	1
Design group	27.60 Gearshift, control
Date	08-08-2016
Validity	Model designation 231.479
Reason for change	
Reason for block	

Complaint:

Fault code U012100, U014600 after software update for transmission control unit

Note:

U012100 - Communication with ESP has a malfunction

U014600 - Communication with central gateway has a malfunction

Cause:

Error in transmission software documentation

Remedy:

Please create a PTSS case with current quicktest and eeprom attached. Case will be sent to Service Engineer for analysis.

Note:

Do not update any additional control units

Symptoms
Power transmission / Automatic transmission / Function / Electrical fault/Fault code

Control unit/fault code		
Control unit	Fault code	Fault text
Y3/8n4 - Fully integrated transmission control (VGS) (VGS4NAG2)	U012100	Communication with ESP has a malfunction. _
Y3/8n4 - Fully integrated transmission control (VGS) (VGS4NAG2)	U014600	Communication with the central gateway has a malfunction. _

