

## Map pocket on front seat backrest trim does not close

Topic number	LI91.10-P-063347
Version	5
Design group	91.10 Front seats
Date	11-21-2016
Validity	Model series 222 as of start of production (SOP) up to WDD2220331A233180 (October 2015) Model series 217 as of SOP up to October 2015 Model series 205 with SA code 30P as of SOP up to April 2016
Reason for change	Damage codes expanded and model designations adjusted
Reason for block	

### Complaint:

The tensioning strap for the map pocket on the front seat backrest trim does not have any tension, so the map pocket no longer closes by itself.

Attachments	
File	Description
Pic. 1.jpg	Map pocket no longer closes

### Cause:

Loss of tension may be caused by embrittlement of elastic band because of high heat levels in the vehicle.

### Remedy:

Replacement of affected backrest trim.

Symptoms
Body / Seat / Seat adjustment / Function error
Body / Seat / Seat adjustment / Does not lock

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			81A34 38	Left front seat backrest stowage net/magazine pocket, W/S205 I 222
			81N34 38	Right front seat backrest stowage net/magazine pocket, W/S205 I 222

# XENTRY TIPS

---

			91A12 38	Left front seat backrest trim, BR217
			91N12 38	Right front seat backrest trim, BR217

WIS-References			
Document number	Title	Note	Allocation
AR91.10-P-1910LF	Remove/install seat-back lining on front seat backrest		Remedy

Attachments
-------------

# XENTRY TIPS

---

Pic. 1.jpg:



# XENTRY TIPS

---

---