



Technical Journal

TITLE:

Headlamp, abnormal moisture/water leakage

REF NO:
TJ 25705

ISSUING DEPARTMENT:
Technical Service

CAR MARKET:
United States and Canada

PARTNER:
3 US 7510 Volvo Car USA

ISSUE DATE:
2016-01-06

STATUS DATE:
2016-03-24

FUNC GROUP:
3521

FUNC DESC:
Headlamp, complete

Page 1 of 3

“Right first time in Time”

Attachment

File Name	File Size
TJ25705.JPG	0.0323 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
134							2011-2012		0000194-0101293	201020-201139

CSC Customer Symptom Codes

Code	Description
W4	Headlights/Moisture/mist on inside of lens

VST Operation Number

VST Operation Number	Description
35203-2	Headlamp assembly one side

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.



Text

* Chassis updated

DESCRIPTION:

The headlamp may have abnormal moisture/water leakage at the inside of the headlamp lens. Possibly caused by a bad sealing.

PRODUCT MODIFICATION:

Improved process at supplier from chassis number shown in the header.

MATERIAL RETURN:

Only if requested in Vehicle Report.

VEHICLE REPORT:

Only if the symptom occurs after breakpoint 2011w39. Use concern area "Vehicle Report" and sub concern area "Support Not Needed". Add a photo of the production label on the headlamp, see attachment TJ25705.jpg.

SERVICE:

In case of customer complaints perform TJ 17076 headlamp leak test.

To view TJ attachment continue to next page. This TJ has one attachment.

