



# Technical Journal

TITLE:

**XC90 T8 DTC IEM-P0A1B47**

<b>REF NO:</b> TJ 31247	<b>ISSUING DEPARTMENT:</b> Technical Service	<b>CAR MARKET:</b> United States and Canada	
<b>PARTNER:</b> 3 US 7510 Volvo Car USA		<b>ISSUE DATE:</b> 2016-04-19	<b>STATUS DATE:</b> 2016-04-21
<b>FUNC GROUP:</b> 4600	<b>FUNC DESC:</b> Rear axle, drive shaft	Page 1 of 2	

“Right first time in Time”

## Attachment

## Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256	BC	B1BPHEV					2016-2016	21	-	201526-201614

## CSC Customer Symptom Codes

Code	Description
MU	4-wheel/all wheel drive/Does not work

## VST Operation Number

## DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
IEM	P0A1B47	Permanent

## Text

### DESCRIPTION:

IEM = Inverter Electronic Module

For DTC IEM-P0A1B47, follow procedure under **SERVICE**.

**SERVICE:**

Perform an IEM Upgrade.

Confirm that all other software is latest status.

**VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 4600.