



AUTOMOBILE DIVISION
American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

VEHICLE IDENTIFICATION NUMBER ► XXXXXXXXXXXXXXXXXXXX JY5



JY5

*****AUTO**MIXED AADC 926



▼ PLEASE DETACH, SIGN BELOW AND PLACE IN RETURN ENVELOPE ▼

INFORMATION CHANGE CARD

PLEASE PROVIDE NAME AND ADDRESS CORRECTIONS ON THE REVERSE SIDE

XXXXXXXXXXXXXXXXXXXX

◀ VEHICLE IDENTIFICATION NUMBER JY5

PLEASE SIGN AND RETURN THIS CARD ONLY IF YOU HAVE MADE CHANGES

I no longer own the vehicle. It was:

- Sold (*print name and address of new owner on reverse, if known*)
- Exported
- Destroyed
- Stolen
- Lease expired, vehicle returned.
- Other: _____

Nota:
Si usted necesita esta información en español por favor comuníquese con Servicio al Cliente de Automóviles Honda al 1-888-234-2138.

Signature: **X**

Date: _____

SIGNATURE OF REGISTERED OWNER OR LESSEE REQUIRED





AUTOMOBILE DIVISION
American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

April 2016

Product Update: Roof Molding

This notice applies to your vehicle: XXXXXXXXXXXXXXXXXXXX

Dear :

On some 2016 Pilot vehicles, the roof molding retaining clips are spread too far apart. In high crosswinds, there is a possibility that the molding may detach.

What should you do?

Call any Honda dealer and make an appointment to have your vehicle repaired. The dealer will replace the existing molding clips and add additional ones.

Lessor Information

Please forward a copy of this notice to the lessee.

What to do if you feel this notice is in error

Our records show that you are the current owner or lessee of a 2016 Pilot involved in this product update. If this is not the case, or the name/address information is not correct, please fill out and return the enclosed, postage-paid Information Change Card. We will then update our records.

If you have questions

If you have any questions about this notice, or need assistance with locating a Honda dealer, please call Honda Automobile Customer Service at 1-888-234-2138. You can also locate a dealer online at *Hondacars.com*.

We apologize for any inconvenience this campaign may cause you.

Sincerely,

American Honda Motor Co., Inc.
Honda Automobile Division

Abril del 2016

Actualización de producto: Molduras del techo

Esta Notificación aplica a su vehículo: XXXXXXXXXXXXXXXXXXXX

Estimado :

En algunos vehículos Pilot 2016, los sujetadores retenedores de las molduras del techo están muy esparcidos. En vientos cruzados altos, hay una posibilidad que la moldura se pueda desprender.

¿Qué debe hacer?

Llame a cualquier concesionario Honda y haga una cita para la reparación de su vehículo. El concesionario reemplazará los sujetadores de las molduras existentes y agregará unos adicionales.

Información para el arrendador

Por favor envíe una copia de esta notificación al arrendatario.

Qué debe hacer si considera que esta notificación es errónea

Nuestros registros muestran que usted es el propietario o arrendatario actual de un vehículo Pilot 2016 el cual forma parte de esta actualización de producto. Si no es el caso, o si la información de nombre/dirección no está correcta, por favor llene y devuelva la tarjeta de cambio de Información anexa con el porte pagado. Con esto actualizaremos nuestros registros.

Si tiene preguntas

Si tiene preguntas acerca de ésta notificación o si necesita asistencia para ponerse en contacto con un concesionario Honda, por favor comuníquese con Atención al Cliente de Automóviles Honda al 1-888-234-2138. Usted también puede ubicar un concesionario en línea en *Hondacars.com*.

Le pedimos disculpas por cualquier inconveniente que ésta campaña pudiera causarle.

Atentamente,

American Honda Motor Co., Inc.
División Automotriz de Honda



AUTOMOBILE DIVISION
American Honda Motor Co., Inc.
P.O. Box 26889
Santa Ana, CA 92799-9751

PRESORTED
FIRST-CLASS MAIL
U.S. POSTAGE PAID
AMERICAN HONDA
MOTOR CO., INC.
92799

FIRST-CLASS MAIL

IMPORTANT: PRODUCT ADVISORY ENCLOSED

PLEASE OPEN IMMEDIATELY

IMPORTANT: Product Advisory Enclosed

