



Home View Content Other Applications As Built Data MyMazda IDS / Infotainment Training Special Service Tools & Current MRT List Return To Search Results Print Help Change Locale

VIN Or Model Year Model Search Term TSB

Body and Accessories
 Brakes
 Driveline / Axle
 Engine
 General Information
 HVAC
 i-ACTIVSENSE
 i-ELOOP
 Multiplex Communication System
 Personalization Features
 Restraints
 Steering
 Suspension
 Transmission / Transaxle
 Wiring Diagram

Home > M-Tips

M-TIPS

To contribute repair tip ideas, send an e-mail to mtips@mazdausa.com or fax to (949) 442-6599. If we select your repair tip, you will receive \$50 value in Reward Performance by Mazda (RPM) points for your efforts. All contributions become property of MNAO, which assumes permission to publish them without further consideration.

2016

FEBRUARY 2016

- MULTI-MODEL (EQUIPPED WITH SKYACTIV-DRIVE) - ATF COLOR DETERIORATION (<https://portal.mazdausa.com/pinquiras/mazdaesi/index?page=detail&id=MT1021>)
- 2007-2015 CX-9, 2009-2013 MAZDA6 3.7L - COOLANT LEAK BEHIND ALTERNATOR (<https://portal.mazdausa.com/pinquiras/mazdaesi/index?page=detail&id=MT1022>)
- 2015 CX-5 - CONNECTOR C-04 AND C-08 SERVICE CAUTION (<https://portal.mazdausa.com/pinquiras/mazdaesi/index?page=detail&id=MT1023>)
- 2016 CX-3 - MANUAL DRIVER'S SEAT MOVES DOWN BY ITSELF (<https://portal.mazdausa.com/pinquiras/mazdaesi/index?page=detail&id=MT1024>)
- MULTI-MODEL (EQUIPPED WITH MAZDA CONNECT) - WRONG SPEED LIMITS SHOWN IN COUNTRY INFORMATION (<https://portal.mazdausa.com>)

JANUARY 2016