

MAZDA T-TIPS – MARCH, 2016

- 2014-2016 MAZDA3 – AD-DISPLAY CAUTION
- 2016 MAZDA6 – AD-DISPLAY CAUTION

SUMMARY: Some customers may claim that it is impossible or difficult to view the Active Driving Display, even if the position of the display is adjusted through the Settings screen. This is caused by an incorrectly learned zero-point (closed position) of the Active Driving Display. The main reason this happens is because an object (e.g. gloves, paper, etc.) was placed in the storage area where the mirror and optical receiver are housed.

- 2014-2016 MAZDA3 (WITH MAZDA CONNECT) – DISPLAY FLICKERS

SUMMARY: Some customers may complain about a MAZDA CONNECT display screen flickering on and off. This may be caused by poor terminal contact at the engine compartment ACC Relay.

- 2016 CX-3 – (WITH MANUAL HVAC) – HVAC TIPS
- 2013-2016 CX-5 – (WITH MANUAL HVAC) – HVAC TIPS
- 2007-2012 CX-7 – (WITH MANUAL HVAC) – HVAC TIPS
- 2007-2016 CX-9 – (WITH MANUAL HVAC) – HVAC TIPS
- 2007-2016 MX-5 – (WITH MANUAL HVAC) – HVAC TIPS
- 2004-2011 RX-8 – (WITH MANUAL HVAC) – HVAC TIPS
- 2011-2016 MAZDA2 – (WITH MANUAL HVAC) – HVAC TIPS
- 2007-2016 MAZDA3 – (WITH MANUAL HVAC) – HVAC TIPS
- 2007-2015 MAZDA5 – (WITH MANUAL HVAC) – HVAC TIPS
- 2007-2016 MAZDA6 – (WITH MANUAL HVAC) – HVAC TIPS

SUMMARY: This article provides HVAC heater/defroster operating tips using Mode selector dial. This includes the use of intermediate positions.

- 2016 CX-3 – (WITH MAZDA CONNECT) – NAVI SD CARD CAUTION
- 2013-2016 CX-5 – (WITH MAZDA CONNECT) – NAVI SD CARD CAUTION
- 2007-2012 CX-7 – (WITH MAZDA CONNECT) – NAVI SD CARD CAUTION
- 2007-2016 CX-9 – (WITH MAZDA CONNECT) – NAVI SD CARD CAUTION
- 2007-2016 MX-5 – (WITH MAZDA CONNECT) – NAVI SD CARD CAUTION
- 2004-2011 RX-8 – (WITH MAZDA CONNECT) – NAVI SD CARD CAUTION
- 2011-2016 MAZDA2 – (WITH MAZDA CONNECT) – NAVI SD CARD CAUTION
- 2007-2016 MAZDA3 – (WITH MAZDA CONNECT) – NAVI SD CARD CAUTION
- 2007-2015 MAZDA5 – (WITH MAZDA CONNECT) – NAVI SD CARD CAUTION
- 2007-2016 MAZDA6 – (WITH MAZDA CONNECT) – NAVI SD CARD CAUTION

SUMMARY: When installing a navigation SD card, confirm that the card is unlocked. Also, Mazda Does Not Recommend swapping navigation system SD cards from one vehicle to another for testing. If swapped, the SD card that is installed into the other vehicle becomes “linked” to the VIN of that vehicle.

- 2016 CX-3 – (WITH REAR VIEW MONITOR) – REAR VIEW MONITOR BLURRY
- 2013-2016 CX-5 – (WITH REAR VIEW MONITOR) – REAR VIEW MONITOR BLURRY
- 2007-2012 CX-7 – (WITH REAR VIEW MONITOR) – REAR VIEW MONITOR BLURRY
- 2007-2016 CX-9 – (WITH REAR VIEW MONITOR) – REAR VIEW MONITOR BLURRY
- 2007-2016 MX-5 – (WITH REAR VIEW MONITOR) – REAR VIEW MONITOR BLURRY
- 2004-2011 RX-8 – (WITH REAR VIEW MONITOR) – REAR VIEW MONITOR BLURRY
- 2011-2016 MAZDA2 – (WITH REAR VIEW MONITOR) – REAR VIEW MONITOR BLURRY
- 2007-2016 MAZDA3 – (WITH REAR VIEW MONITOR) – REAR VIEW MONITOR BLURRY
- 2007-2015 MAZDA5 – (WITH REAR VIEW MONITOR) – REAR VIEW MONITOR BLURRY
- 2007-2016 MAZDA6 – (WITH REAR VIEW MONITOR) – REAR VIEW MONITOR BLURRY

SUMMARY: Some customers may complain about a blurry rear view monitor display. This may be caused by an aftermarket accessory device.

- 2016 CX-3 – TIRE JACK RATTLE
- 2013-2016 CX-5 – TIRE JACK RATTLE
- 2007-2012 CX-7 – TIRE JACK RATTLE
- 2007-2016 CX-9 – TIRE JACK RATTLE
- 2007-2016 MX-5 – TIRE JACK RATTLE
- 2004-2011 RX-8 – TIRE JACK RATTLE
- 2011-2016 MAZDA2 – TIRE JACK RATTLE
- 2007-2016 MAZDA3 – TIRE JACK RATTLE
- 2007-2015 MAZDA5 – TIRE JACK RATTLE
- 2007-2016 MAZDA6 – TIRE JACK RATTLE

SUMMARY: Some customers may complain about a rattle type noise coming from the rear of the vehicle when driving on rough roads. This may be caused by a loose spare tire jack.