

MAZDA TECHNICAL SERVICE BULLETINS – MARCH, 2016

RELEASED 3/31/2016

- [09-021/16 - 2016 MX-5 - CONVERTIBLE TOP INNER CLOTH FALLING DOWN CAUSING POOR APPEARANCE AND OBSTRUCTING VIEW OF BACK WINDOW](#)
- [09-022/16 - 2013-2016 CX-5 - A-PILLAR TRIM DISTORTION](#)
- [15-001/16 - MULTI-MODEL - LDWS OR HBC WARNING LIGHT ON WITH DTC C1001:92](#)

RELEASED 3/29/2016

- [09-020/16 - MULTI-MODEL - CRACKS AROUND EDGE OF ACTIVE DRIVING DISPLAY \(LOOKS FUZZY\)](#)

RELEASED 3/24/2016

- [09-019/16 - 2016 MX-5 - CONSOLE MAT WARPING CAUSING POOR APPEARANCE](#)
- [09-018/16 - 2016 MX-5 - SCRATCH ON SEAT BACK BAR GARNISH FROM CONTACT WITH CONVERTIBLE TOP](#)

RELEASED 3/21/2016

[02-005/16 - MULTI-MODEL - FRONT / REAR STABILIZER NOISE PREVENTION](#)

RELEASED 3/17/2016

- [03-002/16 - 2006-2013 MX-5 - WHINING NOISE FROM REAR DIFFERENTIAL](#)
- [09-017/16 - 2007-2015 CX-9 - RATTLE AND/OR WIND NOISE FROM FRONT DOOR GLASS AREA](#)

RELEASED 3/11/2016

- [09-014/16 - 2013-2016 CX-5 - WHITE MILKY STAINS ON INNER SURFACE OF HEADLIGHT LENS](#)

RELEASED 3/10/2016

- [02-010/16 - MULTI-MODEL - KNOCKING / SQUEAKING NOISE FROM FRONT SHOCK ABSORBER, CREAKING NOISE FROM FRONT LOWER ARM BUSHING](#)

RELEASED 3/07/2016

- [01-009/16 - MULTI-MODEL \(WITH SKYACTIV\) - ROUGH IDLE WITH CHECK ENGINE LIGHT ON AND DTC P0015 / P0524](#)

RELEASED 3/06/2016

- [02-009/16 - MULTI-MODEL - STEERING WHEEL OFF CENTER WITHOUT DRIFT OR PULL](#)
- [09-016/16 - MULTI-MODEL - WRINKLES ON LEATHER SEAT SURFACE OF NEW VEHICLE](#)