



This Service Information bulletin supersedes SI 32 02 14 dated August 2014.

SUBJECT

NEW Installation of Right-Hand Drive Steering Spindle in Left-Hand Drive Vehicle is No Longer Required

MODEL

R50 (Cooper)

R52 (Cooper Convertible, Cooper S Convertible)

R50 (Cooper) R52 (Cooper Convertible, Cooper S Convertible) R53 (Cooper S)

NEW SITUATION

Left-hand drive steering spindles are currently available

NEW CORRECTION

Replace the steering spindle per Repair Instruction 3231070 (REP-RAR5032-3231070, Removing and installing or replacing lower section of steering spindle).

The correct steering spindle is now available

The installation of the right-hand drive steering spindle in left-hand drive vehicles is no longer required.

PARTS INFORMATION

Part Number	Description	Quantity
NEW 32 30 6 870 777	Steering spindle	1
32 20 6 782 616	Self-locking nut	1
32 30 6 758 080	M8x35 Hex bolt	1

WARRANTY INFORMATION

Not applicable.

ATTACHMENTS

View PDF attachment [M320214 Attachment 3231070](#).

View PDF attachment [M320214 Attachment 6131006](#).

View PDF attachment [M320214 Attachment 3233000](#).

[Copyright ©2016 BMW of North America, Inc.]