

8/17/16

MY15, 16

MK

GPOP - Issue Review System

Part Number: 68232878A\$, 68289248A\$, 68289247A\$

Part Description: MODULE, Totally Integrated Power (TIPM)

Issue For MK vehicles ONLY;

Description: If the customer experiences a no start due to dead battery; If the battery is dead due to radiator cooling fan stuck on (Fan runs during battery charging with key off). Before replacing the TIPM for this issue please contact Saji John at cell (248) 890-0324, or Rob Samko at cell (248) 379-4093. If response is not received within 15 minutes, continue with normal repair procedure.~

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.